
Appendix C. Set up Photograph Conducted Emission

Mode 1



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C1 of C5 Issued Date : Jun. 01, 2005

Report No.: FR542927





SIDE VIEW

Mode 2




FRONT VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C2 of C5 Issued Date : Jun. 01, 2005





REAR VIEW



SIDE VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C3 of C5 Issued Date : Jun. 01, 2005



Radiation Emission Antenna A



FRONT VIEW




REAR VIEW

SPORTON International Inc.


TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C4 of C5 Issued Date : Jun. 01, 2005



Antenna B



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C5 of C5 Issued Date : Jun. 01, 2005