




Figure 885: Spurious Emissions at Antenna Terminal 64QAM 15MHz B.W.; 1962.5MHz, 15kHz




Figure 886: Spurious Emissions at Antenna Terminal 64QAM 15MHz B.W.; 1962.5MHz, 30kHz




Figure 887: Spurious Emissions at Antenna Terminal 64QAM 15MHz B.W.; 1962.5MHz, 60kHz




Figure 888: Spurious Emissions at Antenna Terminal 64QAM 15MHz B.W.; 1987.5MHz, 15kHz




Figure 889: Spurious Emissions at Antenna Terminal 64QAM 15MHz B.W.; 1987.5MHz, 30kHz




Figure 890: Spurious Emissions at Antenna Terminal 64QAM 15MHz B.W.; 1987.5MHz, 60kHz




Figure 891: Spurious Emissions at Antenna Terminal 64QAM 20MHz B.W.; 1940.0MHz, 15kHz




Figure 892: Spurious Emissions at Antenna Terminal 64QAM 20MHz B.W.; 1940.0MHz, 30kHz




Figure 893: Spurious Emissions at Antenna Terminal 64QAM 20MHz B.W.; 1940.0MHz, 60kHz




Figure 894: Spurious Emissions at Antenna Terminal 64QAM 20MHz B.W.; 1962.5MHz, 15kHz




Figure 895: Spurious Emissions at Antenna Terminal 64QAM 20MHz B.W.; 1962.5MHz, 30kHz




Figure 896: Spurious Emissions at Antenna Terminal 64QAM 20MHz B.W.; 1962.5MHz, 60kHz




Figure 897: Spurious Emissions at Antenna Terminal 64QAM 20MHz B.W.; 1985.0MHz, 15kHz




Figure 898: Spurious Emissions at Antenna Terminal 64QAM 20MHz B.W.; 1985.0MHz, 30kHz




Figure 899: Spurious Emissions at Antenna Terminal 64QAM 20MHz B.W.; 1985.0MHz, 60kHz




Figure 900: Spurious Emissions at Antenna Terminal 64QAM 25MHz B.W.; 1942.5MHz, 15kHz




Figure 901: Spurious Emissions at Antenna Terminal 64QAM 25MHz B.W.; 1942.5MHz, 30kHz




Figure 902: Spurious Emissions at Antenna Terminal 64QAM 25MHz B.W.; 1942.5MHz, 60kHz




Figure 903: Spurious Emissions at Antenna Terminal 64QAM 25MHz B.W.; 1962.5MHz, 15kHz




Figure 904: Spurious Emissions at Antenna Terminal 64QAM 25MHz B.W.; 1962.5MHz, 30kHz




Figure 905: Spurious Emissions at Antenna Terminal 64QAM 25MHz B.W.; 1962.5MHz, 60kHz




Figure 906: Spurious Emissions at Antenna Terminal 64QAM 25MHz B.W.; 1982.5MHz, 15kHz




Figure 907: Spurious Emissions at Antenna Terminal 64QAM 25MHz B.W.; 1982.5MHz, 30kHz




Figure 908: Spurious Emissions at Antenna Terminal 64QAM 25MHz B.W.; 1982.5MHz, 60kHz




Figure 909: Spurious Emissions at Antenna Terminal 64QAM 40MHz B.W.; 1950.0MHz, 15kHz




Figure 910: Spurious Emissions at Antenna Terminal 64QAM 40MHz B.W.; 1950.0MHz, 30kHz




Figure 911: Spurious Emissions at Antenna Terminal 64QAM 40MHz B.W.; 1950.0MHz, 60kHz




Figure 912: Spurious Emissions at Antenna Terminal 64QAM 40MHz B.W.; 1962.5MHz, 15kHz




Figure 913: Spurious Emissions at Antenna Terminal 64QAM 40MHz B.W.; 1962.5MHz, 30kHz




Figure 914: Spurious Emissions at Antenna Terminal 64QAM 40MHz B.W.; 1962.5MHz, 60kHz




Figure 915: Spurious Emissions at Antenna Terminal 64QAM 40MHz B.W.; 1975.0MHz, 15kHz




Figure 916: Spurious Emissions at Antenna Terminal 64QAM 40MHz B.W.; 1975.0MHz, 30kHz




Figure 917: Spurious Emissions at Antenna Terminal 64QAM 40MHz B.W.; 1975.0MHz, 60kHz




Figure 918: Spurious Emissions at Antenna Terminal 64QAM 50MHz B.W.; 1955.0MHz, 15kHz




Figure 919: Spurious Emissions at Antenna Terminal 64QAM 50MHz B.W.; 1955.0MHz, 30kHz




Figure 920: Spurious Emissions at Antenna Terminal 64QAM 50MHz B.W.; 1955.0MHz, 60kHz




Figure 921: Spurious Emissions at Antenna Terminal 64QAM 50MHz B.W.; 1962.5MHz, 15kHz




Figure 922: Spurious Emissions at Antenna Terminal 64QAM 50MHz B.W.; 1962.5MHz, 30kHz




Figure 923: Spurious Emissions at Antenna Terminal 64QAM 50MHz B.W.; 1962.5MHz, 60kHz




Figure 924: Spurious Emissions at Antenna Terminal 64QAM 50MHz B.W.; 1970.0MHz, 15kHz




Figure 925: Spurious Emissions at Antenna Terminal 64QAM 50MHz B.W.; 1970.0MHz, 30kHz




Figure 926: Spurious Emissions at Antenna Terminal 64QAM 50MHz B.W.; 1970.0MHz, 60kHz




Figure 927: Spurious Emissions at Antenna Terminal 64QAM 60MHz B.W.; 1960.0MHz, 30kHz




Figure 928: Spurious Emissions at Antenna Terminal 64QAM 60MHz B.W.; 1960.0MHz, 60kHz




Figure 929: Spurious Emissions at Antenna Terminal 64QAM 60MHz B.W.; 1962.5MHz, 30kHz




Figure 930: Spurious Emissions at Antenna Terminal 64QAM 60MHz B.W.; 1962.5MHz, 60kHz




Figure 931: Spurious Emissions at Antenna Terminal 64QAM 60MHz B.W.; 1965.0MHz, 30kHz




Figure 932: Spurious Emissions at Antenna Terminal 64QAM 60MHz B.W.; 1965.0MHz, 60kHz




Figure 933: Spurious Emissions at Antenna Terminal 256QAM 5MHz B.W.; 1932.5MHz, 15kHz




Figure 934: Spurious Emissions at Antenna Terminal 256QAM 5MHz B.W.; 1932.5MHz, 30kHz




Figure 935: Spurious Emissions at Antenna Terminal 256QAM 5MHz B.W.; 1962.5MHz, 15kHz




Figure 936: Spurious Emissions at Antenna Terminal 256QAM 5MHz B.W.; 1962.5MHz, 30kHz




Figure 937: Spurious Emissions at Antenna Terminal 256QAM 5MHz B.W.; 1992.5MHz, 15kHz




Figure 938: Spurious Emissions at Antenna Terminal 256QAM 5MHz B.W.; 1992.5MHz, 30kHz




Figure 939: Spurious Emissions at Antenna Terminal 256QAM 10MHz B.W.; 1935.00MHz, 15kHz




Figure 940: Spurious Emissions at Antenna Terminal 256QAM 10MHz B.W.; 1935.00MHz, 30kHz




Figure 941: Spurious Emissions at Antenna Terminal 256QAM 10MHz B.W.; 1935.00MHz, 60kHz




Figure 942: Spurious Emissions at Antenna Terminal 256QAM 10MHz B.W.; 1962.5MHz, 15kHz




Figure 943: Spurious Emissions at Antenna Terminal 256QAM 10MHz B.W.; 1962.5MHz, 30kHz




Figure 944: Spurious Emissions at Antenna Terminal 256QAM 10MHz B.W.; 1962.5MHz, 60kHz




Figure 945: Spurious Emissions at Antenna Terminal 256QAM 10MHz B.W.; 1990.0MHz, 15kHz




Figure 946: Spurious Emissions at Antenna Terminal 256QAM 10MHz B.W.; 1990.0MHz, 30kHz




Figure 947: Spurious Emissions at Antenna Terminal 256QAM 10MHz B.W.; 1990.0MHz, 60kHz




Figure 948: Spurious Emissions at Antenna Terminal 256QAM 15MHz B.W.; 1937.5MHz, 15kHz




Figure 949: Spurious Emissions at Antenna Terminal 256QAM 15MHz B.W.; 1937.5MHz, 30kHz




Figure 950: Spurious Emissions at Antenna Terminal 256QAM 15MHz B.W.; 1937.5MHz, 60kHz




Figure 951: Spurious Emissions at Antenna Terminal 256QAM 15MHz B.W.; 1962.5MHz, 15kHz




Figure 952: Spurious Emissions at Antenna Terminal 256QAM 15MHz B.W.; 1962.5MHz, 30kHz




Figure 953: Spurious Emissions at Antenna Terminal 256QAM 15MHz B.W.; 1962.5MHz, 60kHz




Figure 954: Spurious Emissions at Antenna Terminal 256QAM 15MHz B.W.; 1987.5MHz, 15kHz




Figure 955: Spurious Emissions at Antenna Terminal 256QAM 15MHz B.W.; 1987.5MHz, 30kHz




Figure 956: Spurious Emissions at Antenna Terminal 256QAM 15MHz B.W.; 1987.5MHz, 60kHz




Figure 957: Spurious Emissions at Antenna Terminal 256QAM 20MHz B.W.; 1940.0MHz, 15kHz




Figure 958: Spurious Emissions at Antenna Terminal 256QAM 20MHz B.W.; 1940.0MHz, 30kHz




Figure 959: Spurious Emissions at Antenna Terminal 256QAM 20MHz B.W.; 1940.0MHz, 60kHz