

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission **[Sleeve antenna]**




Photo 1




Photo 2

Radiated Spurious Emission
[Embedded antenna]




Photo 1






Photo 2

Worst Case Position
(EUT-module: Horizontal X-axis / Vertical: X-axis:)


X-axis



Y-axis



Z-axis




Worst Case Position
(Sleeve Antenna: Horizontal X0-axis / Vertical: X90-axis:)

X0-axis



X90-axis



Y0-axis



Y90-axis



Z0-axis



Z90-axis



UL Japan, Inc.

Ise EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999


Facsimile : +81 596 24 8124

Worst Case Position
(Embedded Antenna: Horizontal X-axis / Vertical: Y-axis:)


X-axis




Y-axis(1)




Y-axis(2)



Z-axis(1)



Z-axis(2)



End of Report