

Response to E05-000189-1 and E05-000189-1 IC

E05-000189-1

1. Please revise the 731 form FCC ID to be E675JS0071.
2. A new test report has been uploaded.
3. Powerwave policy is to test the amplifiers at the highest output possible. The actual rated power will usually be less (margin).

E05-000189-1 IC

1. A new general agreement has not yet been signed.