
## Appendix C. Set up Photograph

## Conducted Emission



**FRONT VIEW** 

**REAR VIEW** 

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C1 of C3 Issued Date : Mar. 30, 2005


Report No.: FR532118






SIDE VIEW

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C2 of C3
Issued Date : Mar. 30, 2005



## **Radiation Emission**



FRONT VIEW

**REAR VIEW** 

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255