

The Singing Machine Company, Inc.
6301 NW 5th Way, Suite 2900, Fort Lauderdale, FL, 33309, U.S.A.

Jun.02, 2022

Office of Engineering Technology
Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046
USA

Subject: Explanation of differences between product types

FCC ID: 2AAXO-SML385UZZ

Models: SML385U, SML385UBK, SML385UW, SML385BT,
SML385BTW, SML385BTBK, SML392BT, SML392BTBK,
SML392BTW, SML385UP, SML385BTXX, SML392BTXX,
SML385UXX (XX means unit color, it can be A to Z or N/A)


To Whom It May Concern:

We, The Singing Machine Company, Inc. hereby declare that the model :
SML385U is identical with the model : SML385UBK, SML385UW, SML385BT,
SML385BTW, SML385BTBK, SML392BT, SML392BTBK, SML392BTW,
SML385UP, SML385BTXX, SML392BTXX, SML385UXX (XX means unit color, it
can be A to Z or N/A), except the model names and the color of appearance.

Except for the different above, no other modification is performed.

Sincerely,

The Singing Machine Company, Inc.
Signature:

A handwritten signature in black ink that reads "Gary Atkinson". The signature is written in a cursive, slightly slanted style.

[Gary Atkinson, General Manager]