



Cisco Systems, Inc
170 West Tasman Drive
San Jose, CA 95134

May 26, 2015,

Subject: SDR Software and Configuration Control
New FCC ID: LDKIW3702
Original FCC ID: LDK102087P

Dear Regulatory Authority,

Per KDB 178919 D01 section 6j), we (Cisco Systems, Inc.) attest that all software, configuration, and maintenance for both original and new FCC ID are maintained by the same original grantee.

Note: The original FCC ID and grant and the new FCC ID and grant belong to the same grantee, Cisco Systems and the grantee retains full responsibility for security and configuration control for both FCC IDs and grants

If you have any questions regarding this application, please feel free to contact me.

Best Regards

A handwritten signature in blue ink that reads "Steve Granzella".

Steve Granzella
Compliance Engineering Manager
Cisco Systems, Inc