

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission




Photo 1




Photo 2

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Worst Case Position Transmitter/Receiver (Horizontal: X-axis/ Vertical:Y-axis)
Worst Case Position Frequency Synthesizer (Horizontal: X-axis/ Vertical:X-axis)

X-axis



Y-axis



X-axis



Y-axis



Z-axis




Worst Case Position Signal Processor (Horizontal: X-axis/ Vertical:X-axis)
Worst Case Position PA (Horizontal: X-axis/ Vertical:X-axis)

X-axis



Y-axis



Z-axis



X-axis



Y-axis



Z-axis



Worst Case Position Harmonics Filter (Horizontal: X-axis/ Vertical:X-axis)
Worst Case Position Transceiver (Horizontal: X-axis/ Vertical:X-axis)

X-axis



Y-axis




Z-axis



X-axis



Y-axis



Z-axis



End of Report