



FCC Label:



MICROWAVE OVEN
MODEL: EM9P022PS-P
POWER SUPPLY:120V~ 60Hz
RATED INPUT(MICROWAVE):1400W
RATED OUTPUT(MICROWAVE): 900W
MICROWAVE OUTPUT FREQUENCY:2450MHZ
MANUFACTURE DATE:MM.YYYY
FCC ID:VG8XM9P02YYP
HOUSEHOLD USE ONLY
(NOT FOR COMMERCIAL USE)
THIS DEVICE COMPLIES WITH DHHS
RADIATION PERFORMANCE
STANDARDS 21 CFR SUBCHAPTER J.
MADE IN CHINA
Guangdong Midea Kitchen Appliances
Manufacturing Co.,Ltd.
No.6,Yong An Road,Beijiao,Shunde,Foshan.




LISTED
54NJ
E214180

CAUTION -THIS DEVICE IS TO BE SERVICED ONLY BY PROPERLY QUALIFIED SERVICE PERSONNEL. CONSULT THE SERVICE MANUAL FOR PROPER SERVICE PROCEDURES TO ASSURE CONTINUED COMPLIANCE WITH THE FEDERAL PERFORMANCE STANDARD FOR MICROWAVE OVENS AND FOR PRECAUTIONS TO BE TAKEN TO AVOID POSSIBLE EXPOSURE TO EXCESSIVE MICROWAVE ENERGY.

WARNING - TO ENSURE CONTINUED PROTECTION AGAINST ELECTRICAL SHOCK HAZARD, CONNECT TO PROPERLY GROUNDED OUTLETS ONLY.DISCONNECT APPLIANCE BEFORE SERVICING. REMOVAL OF OUTER CASE WITH PRODUCT ENERGIZED MAY EXPOSE SERVICEMAN TO HAZARDOUS HIGH VOLTAGE POTENTIALS.

- CERTAIN INTERNAL PARTS ARE INTENTIONALLY NOT GROUNDED AND MAY PRESENT A RISK OF ELECTRIC SHOCK ONLY DURING SERVICING.SERVICE PERSONNEL -DO NOT CONTACT THE FOLLOWING PARTS WHILE THE APPLIANCE IS ENERGIZED: IF PROVIDED FAN MOTOR, TURNTABLE MOTOR, DAMPER MOTOR,L.V.TRANSFORMER (TOUCH CONTROL TYPE) OR TIMER MOTOR ASSEMBLY (MECHANICAL TYPE).
- RISK OF ELECTRIC SHOCK. NON-REMOVABLE FASTENERS ARE PROVIDED BECAUSE OF INTERNAL HIGH VOLTAGES. DO NOT REMOVE FASTENERS.
- NOT FOR BUILT-IN INSTALLATION.



WARNING:Cancer and Reproductive Harm-www.p65warnings.ca.gov

FCC Label Location:

