

US Tech Test Report
FCC ID:
IC:
Test Report Number:
Issue date:
Customer:
Model:

FCC Part 15.209 an IC RSS-210 Certification
KE3-3003274
2721A-3003274
18-0038
May 25, 2018
Radio Systems Corp
300-3274

INTERNAL PHOTOGRAPHS



Figure 1. EUT, Battery Compartment Open

US Tech Test Report
FCC ID:
IC:
Test Report Number:
Issue date:
Customer:
Model:

FCC Part 15.209 an IC RSS-210 Certification
KE3-3003274
2721A-3003274
18-0038
May 25, 2018
Radio Systems Corp
300-3274



Figure 2. EUT Enclosure Opened

US Tech Test Report
FCC ID:
IC:
Test Report Number:
Issue date:
Customer:
Model:

FCC Part 15.209 an IC RSS-210 Certification
KE3-3003274
2721A-3003274
18-0038
May 25, 2018
Radio Systems Corp
300-3274



Figure 3. EUT Internal View

US Tech Test Report
FCC ID:
IC:
Test Report Number:
Issue date:
Customer:
Model:

FCC Part 15.209 an IC RSS-210 Certification
KE3-3003274
2721A-3003274
18-0038
May 25, 2018
Radio Systems Corp
300-3274



Figure 4. Coil Loop Antenna Side 1

US Tech Test Report
FCC ID:
IC:
Test Report Number:
Issue date:
Customer:
Model:

FCC Part 15.209 an IC RSS-210 Certification
KE3-3003274
2721A-3003274
18-0038
May 25, 2018
Radio Systems Corp
300-3274




Figure 5. Coil Loop Antenna, Side 2

US Tech Test Report
FCC ID:
IC:
Test Report Number:
Issue date:
Customer:
Model:

FCC Part 15.209 an IC RSS-210 Certification
KE3-3003274
2721A-3003274
18-0038
May 25, 2018
Radio Systems Corp
300-3274




Figure 6. PCB, Component Side

US Tech Test Report
FCC ID:
IC:
Test Report Number:
Issue date:
Customer:
Model:

FCC Part 15.209 an IC RSS-210 Certification
KE3-3003274
2721A-3003274
18-0038
May 25, 2018
Radio Systems Corp
300-3274




Figure 7. Back of PCB with IR Sensor