



FCC ID: DO4EMRLDUP

3 EQUIPMENT UNDER TEST

3.1 Photo documentation of the EuT



FCC ID: DO4EMRLDUP





FCC ID: DO4EMRLDUP

GlobTek PSU:



3.2 Ferrite Locations



FCC ID: DO4EMRLDUP



Ferrite Locations:

1. Fair Rite P/N 284760 (Order No 0443806406) – Add a ferrite on the end of the People Counter Sensor Cable with three turns through the ferrite.
2. Fair Rite P/N 7118986 (Order No B6429-L618-X35) – Add a ferrite on each end of the Badge Board Cable with three turns through the ferrite.
3. Fair Rite P/N (Order No 2865-000-202) – Add two ferrites on the end of the Tx1 and Tx2 connection with one turn.
4. Fair Rite P/N 284760 (Order No 0443806406) – Add a ferrite on the end of the DC Output cable of the GlobTek PSU with three turns through the ferrite.