

Dear Douglas

Acturally, there is only one HOST "T40" for the module (5 antennas). That's why the test result only one configuration. Client asked to apply the module as a Limited module approval for Laptop IBM T40, so the extender did not be used. As client did not allow us to take off the laptop cap for antenna photos. Therefore, they provided us the photo with those IBM laptops (the client only has one T40, so they used other types of laptop for the antenna configuration, those labtops may do the permissive change in future.) I hope the explanation can satisfy the comments, any further questions or comments, please do not hesitate to contact with me. Thanks a lot.

Best Regards,

林文斌 / Eric Lin

ADT Corp. Hsinchu Div.

TEL: +886-3-593-5343 #1719 FAX: +886-3-593-5342

e-mail: eric@adt.com.tw

web-site: www.adt.com.tw

mobile: 0921-197-045