



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 2.APR.2022 15:56:04

Band 2_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 2.APR.2022 15:56:26

Band 2_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 2.APR.2022 15:57:01

Band 2_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 2.APR.2022 15:57:20

Band 2_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 2.APR.2022 15:57:48

Band 2_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 2.APR.2022 15:58:11

Band 2_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 2.APR.2022 15:58:40

Band 2_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 2.APR.2022 15:59:08

Band 2_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 2.APR.2022 15:59:40

Band 2_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 2.APR.2022 16:00:08

Band 2_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:00:49

Band 2_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 2.APR.2022 16:01:15

Band 2_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:01:50

Band 2_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 2.APR.2022 16:02:06

Band 2_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:02:38

Band 2_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 2.APR.2022 16:03:03

Band 2_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:03:38

Band 2_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 2.APR.2022 16:04:00

Band 2_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:04:41

Band 2_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 2.APR.2022 16:05:00

Band 2_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:05:37

Band 2_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 2.APR.2022 16:05:59

Band 2_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:06:34

Band 2_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 2.APR.2022 16:07:02

Band 2_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:07:44

Band 2_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 2.APR.2022 16:08:10

Band 2_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:08:51

Band 2_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 2.APR.2022 16:09:17

Band 2_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:10:01

Band 2_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 2.APR.2022 16:10:27

Band 2_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:11:06

Band 2_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 2.APR.2022 16:11:25

Band 2_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:12:04

Band 2_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 2.APR.2022 16:12:29

Band 2_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:13:14

Band 2_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 2.APR.2022 16:13:36

Band 5_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:14:11

Band 5_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 2.APR.2022 16:14:43

Band 5_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:15:15

Band 5_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 2.APR.2022 16:15:40

Band 5_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:16:12

Band 5_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 2.APR.2022 16:16:34

Band 5_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:17:07

Band 5_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 2.APR.2022 16:17:32

Band 5_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:18:01

Band 5_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 2.APR.2022 16:18:30

Band 5_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:19:01

Band 5_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 2.APR.2022 16:19:24

Band 5_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:19:59

Band 5_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 2.APR.2022 16:20:21

Band 5_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:20:50

Band 5_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 2.APR.2022 16:21:15

Band 5_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:21:47

Band 5_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 2.APR.2022 16:22:09

Band 5_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:22:40

Band 5_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 2.APR.2022 16:23:03

Band 5_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:23:37

Band 5_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 2.APR.2022 16:24:05

Band 5_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:24:39

Band 5_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 2.APR.2022 16:24:58

Band 12_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:25:30

Band 12_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 2.APR.2022 16:25:49

Band 12_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:26:18

Band 12_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 2.APR.2022 16:26:43

Band 12_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:27:15

Band 12_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 2.APR.2022 16:27:37

Band 12_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:28:16

Band 12_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 2.APR.2022 16:28:38

Band 12_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:29:07

Band 12_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 2.APR.2022 16:29:29

Band 12_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:29:58

Band 12_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 2.APR.2022 16:30:17

Band 12_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:30:55

Band 12_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 2.APR.2022 16:31:14

Band 12_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:31:46

Band 12_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 2.APR.2022 16:32:14

Band 12_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:32:49

Band 12_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 2.APR.2022 16:33:11

Band 12_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:33:49

Band 12_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 2.APR.2022 16:34:11

Band 12_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:34:45

Band 12_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 2.APR.2022 16:35:14

Band 12_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:35:51

Band 12_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 2.APR.2022 16:36:19

Band 13_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:36:55

Band13_5 MHz_Low_QPSK_RB25#0_2(763MHz-775MHz)




Date: 24.APR.2022 17:29:17

Band 13_5 MHz_Low_QPSK_RB25#0_3(787MHz-806MHz)




Date: 2.APR.2022 21:48:40

Band 13_5 MHz_Low_QPSK_RB25#0_4(1559MHz-1610MHz)




Date: 24.APR.2022 17:27:22

Band 13_5 MHz_Low_QPSK_RB25#0_5(1GHz-10GHz)




Date: 2.APR.2022 16:37:17

Band 13_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:37:52

Band 13_5 MHz_Middle_QPSK_RB25#0_1(763MHz-775MHz)




Date: 2.APR.2022 21:53:49

Band 13_5 MHz_Middle_QPSK_RB25#0_2(793MHz-806MHz)




Date: 2.APR.2022 21:53:17

Band 13_5 MHz_Middle_QPSK_RB25#0_3(1559MHz-1610MHz)




Date: 24.APR.2022 17:32:15

Band 13_5 MHz_Middle_QPSK_RB25#0_4(1GHz-10GHz)




Date: 2.APR.2022 16:38:20

Band 13_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:38:49

Band 13_5 MHz_High_QPSK_RB25#0_2(763MHz-775MHz)




Date: 2.APR.2022 21:54:23

Band 13_5 MHz_High_QPSK_RB25#0_3(793MHz-806MHz)




Date: 2.APR.2022 21:54:47

Band 13_5 MHz_High_QPSK_RB25#0_4(1559MHz-1610MHz)




Date: 24.APR.2022 17:34:08

Band 13_5 MHz_High_QPSK_RB25#0_5(1GHz-10GHz)




Date: 2.APR.2022 16:39:08

Band 13_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 2.APR.2022 16:39:49

Band 13_10 MHz_Middle_QPSK_RB50#0_2(763MHz-775MHz)




Date: 24.APR.2022 17:36:16

Band 13_10 MHz_Middle_QPSK_RB50#0_3(793MHz-806MHz)




Date: 2.APR.2022 21:57:17

Band 13_10 MHz_MHz_Middle_QPSK_RB50#0_4(1559MHz-1610MHz)




Date: 24.APR.2022 17:34:35

Band 13_10 MHz_Middle_QPSK_RB50#0_5(1GHz-10GHz)




Date: 2.APR.2022 16:40:14

Band 41_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 2.APR.2022 17:59:54

Band 41_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 2.APR.2022 18:00:19

Band 41_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 2.APR.2022 18:00:51

Band 41_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 2.APR.2022 18:01:13

Band 41_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 2.APR.2022 18:01:42

Band 41_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 2.APR.2022 18:02:07

Band 41_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 2.APR.2022 18:02:42

Band 41_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 2.APR.2022 18:03:11

Band 41_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 2.APR.2022 18:03:39

Band 41_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 2.APR.2022 18:04:04

Band 41_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 2.APR.2022 18:04:35

Band 41_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 2.APR.2022 18:05:00

Band 41_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 2.APR.2022 18:05:42

Band 41_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 2.APR.2022 18:06:07

Band 41_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 2.APR.2022 18:06:45

Band 41_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 2.APR.2022 18:07:08

Band 41_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 2.APR.2022 18:07:40

Band 41_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 2.APR.2022 18:08:05

Band 41_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 2.APR.2022 18:08:41

Band 41_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 2.APR.2022 18:09:06

Band 41_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 2.APR.2022 18:09:42

Band 41_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 2.APR.2022 18:10:07

Band 41_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)



Date: 2.APR.2022 18:10:51

Band 41_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)



Date: 2.APR.2022 18:11:17