



TÜV SÜD America Inc., 10040 Mesa Rim Road, San Diego, CA 92121  
Tel: (858) 678-1400. Website: [www.TUVamerica.com](http://www.TUVamerica.com)

June 18, 2018

TUV SUD BABT FCB  
Octagon House, Concorde Way  
Segensworth Rd N, Fareham  
PO15 5RL

RE: IC: 21385-ATD300S  
FCC ID: 2AH4HATD300S

We hereby attest that the above product complies with the latest version of the  
RSS-130 Issue 1 October 2013  
RSS-139 Issue 3 July 2015  
RSS-247 Issue 2 March 16 2017  
RSS-GEN Issue 4 November 13 2014  
FCC Part 27 Subpart C October 2017

The radio test reports supplied in this application:

- Report Number: AT72126480-1C1 for BT LE module MBN52832 issued by TUV SUD America Inc.,
- Report Number: RTWK160705002-00 for Cell Module EC25-V issued by Bay Area Compliance Labs Corp.
- Report Number: JT72138801-0418B for ATD300S issued by TUV SUD America Inc.

support compliance of the modules within this product.

The test results are still valid and applicable with the current requirements.

Sincerely,

Xiaoying Zhang  
EMC/Wireless Test Engineer