




EMC Test Data

Client:	Bastille Networks	PR Number:	PR105382
Model:	Chevy Sensor-2 FCC ID: 2AIJ5-SENSOR2	T-Log Number:	TL105382
Contact:	Ellis Villafuerte	Project Manager:	Christine Krebill
Standard:	FCC 15.121 (Scannig receiver)	Project Engineer:	Deniz Demirci
		Class:	A

Test setup photos





EMC Test Data


Client:	Bastille Networks	PR Number:	PR105382
Model:	Chevy Sensor-2 FCC ID: 2AIJ5-SENSOR2	T-Log Number:	TL105382
Contact:	Ellis Villafuerte	Project Manager:	Christine Krebill
Standard:	FCC 15.121 (Scannig receiver)	Project Engineer:	Deniz Demirci
		Class:	A

Test setup photos



Client:	Bastille Networks	PR Number:	PR105382
Model:	Chevy Sensor-2 FCC ID: 2AIJ5-SENSOR2	T-Log Number:	TL105382
Contact:	Ellis Villafuerte	Project Manager:	Christine Krebill
Standard:	FCC 15.121 (Scannig receiver)	Project Engineer:	Deniz Demirci
		Class:	A

Test setup photos





EMC Test Data


Client:	Bastille Networks	PR Number:	PR105382
Model:	Chevy Sensor-2 FCC ID: 2AIJ5-SENSOR2	T-Log Number:	TL105382
Contact:	Ellis Villafuerte	Project Manager:	Christine Krebill
Standard:	FCC 15.121 (Scannig receiver)	Project Engineer:	Deniz Demirci
		Class:	N/A

Test Configuration Photographs




Client:	Bastille Networks	PR Number:	PR105382
Model:	Chevy Sensor-2 FCC ID: 2AIJ5-SENSOR2	T-Log Number:	TL105382
Contact:	Ellis Villafuerte	Project Manager:	Christine Krebill
Standard:	FCC 15.121 (Scannig receiver)	Project Engineer:	Deniz Demirci
		Class:	N/A

Test Configuration Photographs



Client:	Bastille Networks	PR Number:	PR105382
Model:	Chevy Sensor-2 FCC ID: 2AIJ5-SENSOR2	T-Log Number:	TL105382
Contact:	Ellis Villafuerte	Project Manager:	Christine Krebill
Standard:	FCC 15.121 (Scannig receiver)	Project Engineer:	Deniz Demirci
		Class:	N/A

Test Configuration Photographs





EMC Test Data

Client:	Bastille Networks	PR Number:	PR105382
Model:	Chevy Sensor-2 FCC ID: 2AIJ5-SENSOR2	T-Log Number:	TL105382
Contact:	Ellis Villafuerte	Project Manager:	Christine Krebill
Standard:	FCC 15.121 (Scannig receiver)	Project Engineer:	Deniz Demirci
		Class:	A

Test Configuration Photograph #1
(Conducted Emissions - Power Port)



Client:	Bastille Networks	PR Number:	PR105382
Model:	Chevy Sensor-2 FCC ID: 2AIJ5-SENSOR2	T-Log Number:	TL105382
Contact:	Ellis Villafuerte	Project Manager:	Christine Krebill
Standard:	FCC 15.121 (Scannig receiver)	Project Engineer:	Deniz Demirci
		Class:	A

Test Configuration Photograph #2
(Conducted Emissions - Power Port)

