


Addendum

- This computer is not equipped with PC Card Slots function and Product Recovery CD-ROM.
 - The information related to PC Card Slots and Product Recovery CD-ROM shown in the “Operating Instructions” and “Reference Manual” do not apply to this computer.

Names and Functions of Parts

“OPERATING INSTRUCTIONS”

Add the following “DataTAC Antenna”.



CAUTION

- Communication is performed through the DataTAC Antenna. Do not block the antenna area with your hand or otherwise interfere with the passage of the radio signals.