





APPENDIX G

: INTERNAL PHOTOGRAPHS




<Main PCB Section>




<Main PCB Section>



<Display PCB Section>



<Display PCB Section>




<WPT PCB Section>




<WPT PCB Section>



<WPT PCB Section>




<SMART Buzzer PCB Section>




< SMART Buzzer PCB Section >



<WIFI PCB Section>



<WIFI PCB Section>



<Voice Assistant Section>




< Voice Assistant Section >



<PCB Section>




< Machine Section >



< Machine Section >



< Machine Section >




< Machine Section >



< Machine Section >



< WPT Section >



< WPT Section >



< WPT Section >




< WPT Section >




< WPT Section >




< WPT Section >




< SUB PCB Section >



< SUB PCB Section >




< SUB PCB Section >




< SUB PCB Section >



< SUB PCB Section >



< Machine Section >



< SUB SMPS Section_OLD (EAX66878105) >




< SUB SMPS Section _NEW (EAX66878107)>




< SUB PCB Section_OLD (EAX65001602)>



< SUB PCB Section_NEW (EAX65001605)>




EAX67073305



EAX67073310

< Display PCB Section >



< Display PCB Section_ NEW (EAX67073310)>



< Comp. Section_ OLD (FLD90LANA)>



< Comp. Section_ NEW (FLD165NBMA)>

The end