





APPENDIX D


: INTERNAL PHOTOGRAPHS




<OLD Main PCB Section>




<OLD Main PCB Section>




<NEW Main PCB Section>




<NEW Main PCB Section>




< OLD SUB SMPS Section >




< NEW SUB SMPS Section >




< NEW SUB SMPS Section >



<Display PCB Section>



<Display PCB Section>




<WPT PCB Section>




<WPT PCB Section>




<WPT PCB Section>




<SMART Buzzer PCB Section>




< SMART Buzzer PCB Section >



<WIFI PCB Section>



<WIFI PCB Section>




<Voice Assistant Section>




< Voice Assistant Section >




<PCB Section>



< Machine Section >




< Machine Section >



< Machine Section >




< Machine Section >




< Machine Section >




< WPT Section >



< WPT Section >



< WPT Section >




< WPT Section >




< WPT Section >




< WPT Section >




< SUB PCB Section >



< SUB PCB Section >




< SUB PCB Section >



< SUB PCB Section >




< SUB PCB Section >



< Machine Section >



< SUB PCB Section >



EAX67073305


EAX67073310

< Display PCB Section >



Order Number : GETEC-C1-24-440
Test Report Number : GETEC-E3-24-090

FCC Part 18
Page 40 / 42



< Display PCB Section >



< Comp. Section >

The end