




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>


APPENDIX H: INTERNAL PHOTOGRAPHS



PHOTOGRAPH 7: PCB FRONT (MURS-22)




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 8: PCB BACK (MURS-22)



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 9: PCB FRONT IN CHASSIS (MURS-22)




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 10: INSIDE FRONT COVER (MURS-22)



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 11: INSIDE BACK CHASSIS (MURS-22)



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 12: FRONT OF PCB MOUNTED INSIDE CHASSIS (MURS-25)



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 13: INSIDE OF FRONT COVER (MURS-25)




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 14: BACK WITH BATTERY REMOVED (MURS-25)




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 15: BACK OF PCB (MURS-25)



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 16:BACK OF PCB WITH POSITIVE BATTERY TERMINAL REMOVED (MURS-25)




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 17: FRONT OF PCB (MURS-25)



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 18: FRONT OF PCB WITH LCD REMOVED (MURS-25)