





Report No.: AAEMT/EMC/221128-04-08

### ax40 5.230 GHz



Report No.: AAEMT/EMC/221128-04-08



### ax80 5.210 GHz



Report No.: AAEMT/EMC/221128-04-08



Result plot as follows: CHAIN 0

a20 5.745 GHz





Report No.: AAEMT/EMC/221128-04-08

### a20 5.825 GHz





Report No.: AAEMT/EMC/221128-04-08

### n20 5.745 GHz



Report No.: AAEMT/EMC/221128-04-08



### n20 5.825 GHz







Report No.: AAEMT/EMC/221128-04-08

### n40 5.755 GHz



Report No.: AAEMT/EMC/221128-04-08



### n40 5.795 GHz







Report No.: AAEMT/EMC/221128-04-08

ac20 5.745 GHz





Report No.: AAEMT/EMC/221128-04-08

### ac20 5.825 GHz





Report No.: AAEMT/EMC/221128-04-08

### ac40 5.755 GHz





Report No.: AAEMT/EMC/221128-04-08

### ac40 5.795 GHz





Report No.: AAEMT/EMC/221128-04-08

### ac80 5.775 GHz



Report No.: AAEMT/EMC/221128-04-08



ax20 5.745 GHz







Report No.: AAEMT/EMC/221128-04-08

ax20 5.825 GHz





Report No.: AAEMT/EMC/221128-04-08

### ax40 5.755 GHz





Report No.: AAEMT/EMC/221128-04-08

ax40 5.795 GHz



Report No.: AAEMT/EMC/221128-04-08



ax80 5.775 GHz



Report No.: AAEMT/EMC/221128-04-08



Result plot as follows: CHAIN 1

a20 5.180 GHz



Report No.: AAEMT/EMC/221128-04-08



### a20 5.240 GHz







Report No.: AAEMT/EMC/221128-04-08

### n20 5.180 GHz





Report No.: AAEMT/EMC/221128-04-08

### n20 5.240 GHz





Report No.: AAEMT/EMC/221128-04-08

### n40 5.190 GHz





Report No.: AAEMT/EMC/221128-04-08

### n40 5.230 GHz





Report No.: AAEMT/EMC/221128-04-08

### ac20 5.180 GHz



Report No.: AAEMT/EMC/221128-04-08



ac20 5.240 GHz







Report No.: AAEMT/EMC/221128-04-08

ac40 5.190 GHz





Report No.: AAEMT/EMC/221128-04-08

ac40 5.230 GHz





Report No.: AAEMT/EMC/221128-04-08

### ac80 5.210 GHz





Report No.: AAEMT/EMC/221128-04-08

ax20 5.180 GHz





Report No.: AAEMT/EMC/221128-04-08

ax20 5.240 GHz



Report No.: AAEMT/EMC/221128-04-08



ax40 5.190 GHz







Report No.: AAEMT/EMC/221128-04-08

ax40 5.230 GHz



Report No.: AAEMT/EMC/221128-04-08



ax80 5.210 GHz



Report No.: AAEMT/EMC/221128-04-08



Result plot as follows: CHAIN 1

a20 5.745 GHz





Report No.: AAEMT/EMC/221128-04-08

### a20 5.825 GHz





Report No.: AAEMT/EMC/221128-04-08

### n20 5.745 GHz



Report No.: AAEMT/EMC/221128-04-08



### n20 5.825 GHz







Report No.: AAEMT/EMC/221128-04-08

### n40 5.755 GHz





Report No.: AAEMT/EMC/221128-04-08

### n40 5.795 GHz





Report No.: AAEMT/EMC/221128-04-08

ac20 5.745 GHz





Report No.: AAEMT/EMC/221128-04-08

ac20 5.825 GHz





Report No.: AAEMT/EMC/221128-04-08

ac40 5.755 GHz



Report No.: AAEMT/EMC/221128-04-08



ac40 5.795 GHz







Report No.: AAEMT/EMC/221128-04-08

### ac80 5.775 GHz





Report No.: AAEMT/EMC/221128-04-08

ax20 5.745 GHz





Report No.: AAEMT/EMC/221128-04-08

ax20 5.825 GHz





Report No.: AAEMT/EMC/221128-04-08

### ax40 5.755 GHz





Report No.: AAEMT/EMC/221128-04-08

ax40 5.795 GHz



Report No.: AAEMT/EMC/221128-04-08

ax80 5.775 GHz





## 11. ANTENNA REQUIREMENTS

### 11.1. Limit

15.203 requirement: For intentional device, according to 15.203: an intentional radiator shall be designed to ensure that no antenna other than that furnished by the responsible party shall be used with the device.

### 11.2. EUT ANTENNA

The antennas used for this product an Omni-directional Antenna that no antenna other than that furnished by the responsible party shall be used with the device, the maximum peak gain of the transmit antenna is 5dBi and the antenna connector is designed with permanent attachment and no consideration of replacement. Therefore the EUT is considered sufficient to comply with the provision.



**.\*\*End of report\*\***