## Due Diligence Letter

For Certification Service in the USA

## **Federal Communications Commission**

Equipment Authorization Division, Application Processing Branch 7435 Oakland Mills Road Columbia, MD 21048

To whom it may concern

FCC ID	Model name
2AKLL-AD5X	AD5X

Pursuant to KDB 986446 D01 Covered Equipment Guidance the evaluation of the product above shows compliance for the following reasons:

Compliance	Evaluation process	Results
Inherent compliance	The chipset(s) used is not capable of running the cybersecurity and/or anti-virus software	Compliance
	The memory used does not allow the running the cybersecurity and/or anti-virus software	Compliance
	The storage capacity does not allow the running the cybersecurity and/or anti-virus software	Compliance
	The operating system used is not capable of running the cybersecurity and/or anti-virus software	Compliance
No inherent	Based on software bill of material	Compliance
compliance	Based on scan for running software on the device	
	Based on filesystem scan for cybersecurity and/or anti-virus software	

The equipment for which authorization is sought complies with the rules and fulfils the requirements as detailed in the above mentioned KDB.

## Evaluation performed by

Company Name: MAXLAB Testing Co., Ltd.

Contact Name: Harry Chen

Address: 1/F, Building B, Xinshidai GR Park, Shiyan Street, Bao'an

District, Shenzhen, Guangdong, 518052, People's Republic of

China

Phone: +86-15691418608 Email: <u>harry@att-lab.cn</u>

Signature:

Hovey Chen

Date: 2025-04-17