



50MHz_15kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -46.92 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 02:20:16


50MHz_15kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -37.95 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 02:21:10


50MHz_15kHz_3500MHz_DFT-s-OFDM QPSK_RB1@269 -47.23 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 02:22:00


50MHz_15kHz_3500MHz_DFT-s-OFDM QPSK_RB1@269 -37.87 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 02:22:54


50MHz_15kHz_3500MHz_DFT-s-OFDM QPSK_RB270@0 -37.82 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 02:24:38


50MHz_15kHz_3500MHz_DFT-s-OFDM QPSK_RB270@0 -47.83 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng


Date: 22.MAY.2024 02:23:44

50MHz_15kHz_3525MHz_DFT-s-OFDM QPSK_RB1@0 -47.37 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 02:25:29

50MHz_15kHz_3525MHz_DFT-s-OFDM QPSK_RB1@0 -37.96 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 02:26:23

50MHz_15kHz_3525MHz_DFT-s-OFDM QPSK_RB1@269 -47.19 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 02:27:13

50MHz_15kHz_3525MHz_DFT-s-OFDM QPSK_RB1@269 -38.00 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 02:28:07

50MHz_15kHz_3525MHz_DFT-s-OFDM QPSK_RB270@0 -38.01 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 02:29:51

50MHz_15kHz_3525MHz_DFT-s-OFDM QPSK_RB270@0 -47.07 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 02:28:57

50MHz_30kHz_3475MHz_DFT-s-OFDM QPSK_RB1@0 -37.53 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:55:24

50MHz_30kHz_3475MHz_DFT-s-OFDM QPSK_RB1@0 -45.55 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:54:30

50MHz_30kHz_3475MHz_DFT-s-OFDM QPSK_RB1@132 -46.83 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:56:14

50MHz_30kHz_3475MHz_DFT-s-OFDM QPSK_RB1@132 -37.49 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:57:08

50MHz_30kHz_3475MHz_DFT-s-OFDM QPSK_RB128@0 -37.88 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:59:12

50MHz_30kHz_3475MHz_DFT-s-OFDM QPSK_RB128@0 -47.11 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 09:58:18


50MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -37.09 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 10:00:55


50MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -47.27 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 10:00:01


50MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@132 -47.29 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 10:01:44


50MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@132 -37.75 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 10:02:38


50MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB128@0 -45.97 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 10:03:28


50MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB128@0 -37.69 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng


Date: 22.MAY.2024 10:04:22

50MHz_30kHz_3525MHz_DFT-s-OFDM QPSK_RB1@0 -46.13 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 10:05:25

50MHz_30kHz_3525MHz_DFT-s-OFDM QPSK_RB1@0 -37.46 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 10:06:19

50MHz_30kHz_3525MHz_DFT-s-OFDM QPSK_RB1@132 -47.00 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 10:07:08

50MHz_30kHz_3525MHz_DFT-s-OFDM QPSK_RB1@132 -38.10 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 10:08:02

50MHz_30kHz_3525MHz_DFT-s-OFDM QPSK_RB128@0 -37.39 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 10:09:46

50MHz_30kHz_3525MHz_DFT-s-OFDM QPSK_RB128@0 -47.41 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 10:08:53


60MHz_30kHz_3480MHz_DFT-s-OFDM QPSK_RB1@0 -37.30 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 10:11:31


60MHz_30kHz_3480MHz_DFT-s-OFDM QPSK_RB1@0 -46.32 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 10:10:37


60MHz_30kHz_3480MHz_DFT-s-OFDM QPSK_RB1@161 -47.20 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 10:12:23


60MHz_30kHz_3480MHz_DFT-s-OFDM QPSK_RB1@161 -37.70 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 10:13:17


60MHz_30kHz_3480MHz_DFT-s-OFDM QPSK_RB162@0 -37.54 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 10:15:01


60MHz_30kHz_3480MHz_DFT-s-OFDM QPSK_RB162@0 -47.29 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 10:14:07


60MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -37.83 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 10:16:45


60MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -47.24 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 10:15:51


60MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@161 -38.15 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 10:18:29


60MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@161 -47.02 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 10:17:35


60MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB162@0 -37.76 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng







Date: 22.MAY.2024 10:20:14

60MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB162@0 -46.88 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 10:19:20




70MHz_30kHz_3485MHz_DFT-s-OFDM QPSK_RB1@0 -37.76 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 10:27:16


70MHz_30kHz_3485MHz_DFT-s-OFDM QPSK_RB1@0 -46.80 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 10:26:22


70MHz_30kHz_3485MHz_DFT-s-OFDM QPSK_RB1@188 -37.63 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 10:29:17


70MHz_30kHz_3485MHz_DFT-s-OFDM QPSK_RB1@188 -46.36 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 10:28:23


70MHz_30kHz_3485MHz_DFT-s-OFDM QPSK_RB180@0 -37.58 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 10:31:02


70MHz_30kHz_3485MHz_DFT-s-OFDM QPSK_RB180@0 -47.42 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 10:30:08


70MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -46.81 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 10:31:53


70MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -37.36 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 10:32:47


70MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@188 -37.62 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 10:34:32


70MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@188 -46.14 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 10:33:38


70MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB180@0 -46.65 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 10:35:23


70MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB180@0 -37.70 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng


Date: 22.MAY.2024 10:36:17

70MHz_30kHz_3515MHz_DFT-s-OFDM QPSK_RB1@0 -38.11 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 10:38:03

70MHz_30kHz_3515MHz_DFT-s-OFDM QPSK_RB1@0 -47.32 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 10:37:09

70MHz_30kHz_3515MHz_DFT-s-OFDM QPSK_RB1@188 -47.74 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 10:38:54

70MHz_30kHz_3515MHz_DFT-s-OFDM QPSK_RB1@188 -37.65 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 10:39:49

70MHz_30kHz_3515MHz_DFT-s-OFDM QPSK_RB180@0 -47.42 dBm









ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 10:40:40


70MHz_30kHz_3515MHz_DFT-s-OFDM QPSK_RB180@0 -37.77 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 10:41:34




80MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -37.76 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 19.MAY.2024 03:15:43


80MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -46.95 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 19.MAY.2024 03:14:48


80MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@216 -47.37 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 19.MAY.2024 03:16:37


80MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@216 -37.86 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 19.MAY.2024 03:17:32


80MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB216@0 -46.74 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 19.MAY.2024 03:18:26


80MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB216@0 -37.62 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 19.MAY.2024 03:19:21


80MHz_30kHz_3510MHz_DFT-s-OFDM QPSK_RB1@0 -38.09 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 19.MAY.2024 03:21:12


80MHz_30kHz_3510MHz_DFT-s-OFDM QPSK_RB1@0 -46.52 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 19.MAY.2024 03:20:17


80MHz_30kHz_3510MHz_DFT-s-OFDM QPSK_RB1@216 -47.14 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 19.MAY.2024 03:22:06


80MHz_30kHz_3510MHz_DFT-s-OFDM QPSK_RB1@216 -37.90 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 19.MAY.2024 03:23:01


80MHz_30kHz_3510MHz_DFT-s-OFDM QPSK_RB216@0 -37.41 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 19.MAY.2024 03:24:50


80MHz_30kHz_3510MHz_DFT-s-OFDM QPSK_RB216@0 -47.17 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng


Date: 19.MAY.2024 03:23:55

90MHz_30kHz_3495MHz_DFT-s-OFDM QPSK_RB1@0 -37.73 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 03:26:39

90MHz_30kHz_3495MHz_DFT-s-OFDM QPSK_RB1@0 -47.21 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 03:25:44

90MHz_30kHz_3495MHz_DFT-s-OFDM QPSK_RB1@244 -37.81 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 03:28:27

90MHz_30kHz_3495MHz_DFT-s-OFDM QPSK_RB1@244 -46.61 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 03:27:32

90MHz_30kHz_3495MHz_DFT-s-OFDM QPSK_RB243@0 -47.20 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 03:29:21

90MHz_30kHz_3495MHz_DFT-s-OFDM QPSK_RB243@0 -37.76 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 19.MAY.2024 03:30:16


90MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -37.86 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 19.MAY.2024 03:32:05


90MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -46.97 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 19.MAY.2024 03:31:10


90MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@244 -47.22 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 19.MAY.2024 03:32:58


90MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@244 -37.95 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 19.MAY.2024 03:33:53


90MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB243@0 -47.72 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 19.MAY.2024 03:34:47


90MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB243@0 -38.01 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 19.MAY.2024 03:35:42


90MHz_30kHz_3505MHz_DFT-s-OFDM QPSK_RB1@0 -46.59 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 19.MAY.2024 03:36:36


90MHz_30kHz_3505MHz_DFT-s-OFDM QPSK_RB1@0 -37.76 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 19.MAY.2024 03:37:31


90MHz_30kHz_3505MHz_DFT-s-OFDM QPSK_RB1@244 -47.27 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 19.MAY.2024 03:38:24


90MHz_30kHz_3505MHz_DFT-s-OFDM QPSK_RB1@244 -37.76 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 19.MAY.2024 03:39:19


90MHz_30kHz_3505MHz_DFT-s-OFDM QPSK_RB243@0 -38.16 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 19.MAY.2024 03:41:07


90MHz_30kHz_3505MHz_DFT-s-OFDM QPSK_RB243@0 -46.88 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 19.MAY.2024 03:40:12


100MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -37.96 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 19.MAY.2024 03:42:57


100MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0 -47.76 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 19.MAY.2024 03:42:02


100MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@272 -46.91 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 19.MAY.2024 03:43:51


100MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@272 -37.75 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 19.MAY.2024 03:44:46


100MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB270@0 -46.45 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 19.MAY.2024 03:45:41

100MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB270@0 -37.85 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 19.MAY.2024 03:46:36


n77_3

10MHz_15kHz_3705MHz_DFT-s-OFDM QPSK_RB1@0 -46.74 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 14:02:40

10MHz_15kHz_3705MHz_DFT-s-OFDM QPSK_RB1@0 -35.40 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 14:03:39

10MHz_15kHz_3705MHz_DFT-s-OFDM QPSK_RB1@51 -41.81 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 14:04:31

10MHz_15kHz_3705MHz_DFT-s-OFDM QPSK_RB1@51 -35.24 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 14:05:30

10MHz_15kHz_3705MHz_DFT-s-OFDM QPSK_RB50@0 -35.61 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 14:07:21

10MHz_15kHz_3705MHz_DFT-s-OFDM QPSK_RB50@0 -41.03 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 14:06:22

10MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -46.46 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 14:58:09

10MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -35.41 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 14:59:08

10MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@51 -41.03 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 14:11:31

10MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@51 -35.59 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 14:12:29

10MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB50@0 -40.80 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 14:13:21

10MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB50@0 -35.05 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 14:15:43

10MHz_15kHz_3975MHz_DFT-s-OFDM QPSK_RB1@0 -47.21 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 15:08:43

10MHz_15kHz_3975MHz_DFT-s-OFDM QPSK_RB1@0 -35.23 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 15:09:41

10MHz_15kHz_3975MHz_DFT-s-OFDM QPSK_RB1@51 -35.76 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 15:14:51

10MHz_15kHz_3975MHz_DFT-s-OFDM QPSK_RB1@51 -26.61 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 15:13:53

10MHz_15kHz_3975MHz_DFT-s-OFDM QPSK_RB50@0 -46.85 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 19:04:20

10MHz_15kHz_3975MHz_DFT-s-OFDM QPSK_RB50@0 -35.91 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 19:05:20

10MHz_30kHz_3705MHz_DFT-s-OFDM QPSK_RB1@0 -34.88 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:01:16

10MHz_30kHz_3705MHz_DFT-s-OFDM QPSK_RB1@0 -46.26 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 20:58:51

10MHz_30kHz_3705MHz_DFT-s-OFDM QPSK_RB1@23 -47.38 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:02:10

10MHz_30kHz_3705MHz_DFT-s-OFDM QPSK_RB1@23 -35.09 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:02:32

10MHz_30kHz_3705MHz_DFT-s-OFDM QPSK_RB24@0 -35.36 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:04:23

10MHz_30kHz_3705MHz_DFT-s-OFDM QPSK_RB24@0 -47.33 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:04:05


10MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -47.15 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 21:05:17


10MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -35.65 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 21:05:35


10MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@23 -35.69 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 21:07:18


10MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@23 -47.09 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 21:06:51


10MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB24@0 -47.43 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 21:08:33


10MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB24@0 -35.59 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng


Date: 22.MAY.2024 21:09:15

10MHz_30kHz_3975MHz_DFT-s-OFDM QPSK_RB1@0 -46.71 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:10:26

10MHz_30kHz_3975MHz_DFT-s-OFDM QPSK_RB1@0 -34.89 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:11:11

10MHz_30kHz_3975MHz_DFT-s-OFDM QPSK_RB1@23 -36.19 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:13:39

10MHz_30kHz_3975MHz_DFT-s-OFDM QPSK_RB1@23 -47.47 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:13:01

10MHz_30kHz_3975MHz_DFT-s-OFDM QPSK_RB24@0 -46.07 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:14:35

10MHz_30kHz_3975MHz_DFT-s-OFDM QPSK_RB24@0 -35.49 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:14:56


15MHz_15kHz_3707.5MHz_DFT-s-OFDM QPSK_RB1@0 -46.63 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 19:06:15


15MHz_15kHz_3707.5MHz_DFT-s-OFDM QPSK_RB1@0 -35.51 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 19:07:15


15MHz_15kHz_3707.5MHz_DFT-s-OFDM QPSK_RB1@78 -41.30 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 19:08:05


15MHz_15kHz_3707.5MHz_DFT-s-OFDM QPSK_RB1@78 -35.75 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 19:08:22


15MHz_15kHz_3707.5MHz_DFT-s-OFDM QPSK_RB75@0 -35.63 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 19:09:31


15MHz_15kHz_3707.5MHz_DFT-s-OFDM QPSK_RB75@0 -46.09 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng


Date: 22.MAY.2024 19:09:14

15MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -35.61 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 19:10:43

15MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -45.72 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 19:10:26

15MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@78 -47.09 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 19:11:59

15MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@78 -35.31 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 19:12:16

15MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB75@0 -35.24 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 19:19:10

15MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB75@0 -34.78 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 19:18:15

15MHz_15kHz_3972.5MHz_DFT-s-OFDM QPSK_RB1@0 -44.91 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 19:23:55

15MHz_15kHz_3972.5MHz_DFT-s-OFDM QPSK_RB1@0 -35.35 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 19:24:12

15MHz_15kHz_3972.5MHz_DFT-s-OFDM QPSK_RB1@78 -47.17 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 19:24:59

15MHz_15kHz_3972.5MHz_DFT-s-OFDM QPSK_RB1@78 -35.92 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 19:25:16

15MHz_15kHz_3972.5MHz_DFT-s-OFDM QPSK_RB75@0 -47.22 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 19:26:09

15MHz_15kHz_3972.5MHz_DFT-s-OFDM QPSK_RB75@0 -35.35 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 19:26:40

15MHz_30kHz_3707.5MHz_DFT-s-OFDM QPSK_RB1@0 -35.26 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:16:19

15MHz_30kHz_3707.5MHz_DFT-s-OFDM QPSK_RB1@0 -46.87 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:15:57

15MHz_30kHz_3707.5MHz_DFT-s-OFDM QPSK_RB1@37 -46.35 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:17:21

15MHz_30kHz_3707.5MHz_DFT-s-OFDM QPSK_RB1@37 -35.92 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:17:43

15MHz_30kHz_3707.5MHz_DFT-s-OFDM QPSK_RB36@0 -46.83 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:18:44

15MHz_30kHz_3707.5MHz_DFT-s-OFDM QPSK_RB36@0 -34.98 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:19:06

15MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -35.58 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:21:06

15MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -47.13 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:20:45

15MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@37 -35.55 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:23:31

15MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@37 -46.66 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:22:55

15MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB36@0 -35.83 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:26:09

15MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB36@0 -46.61 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:25:50

15MHz_30kHz_3972.5MHz_DFT-s-OFDM QPSK_RB1@0 -46.53 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:27:03

15MHz_30kHz_3972.5MHz_DFT-s-OFDM QPSK_RB1@0 -36.29 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:27:38

15MHz_30kHz_3972.5MHz_DFT-s-OFDM QPSK_RB1@37 -35.38 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:29:31

15MHz_30kHz_3972.5MHz_DFT-s-OFDM QPSK_RB1@37 -47.20 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:29:13

15MHz_30kHz_3972.5MHz_DFT-s-OFDM QPSK_RB36@0 -46.79 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:30:47

15MHz_30kHz_3972.5MHz_DFT-s-OFDM QPSK_RB36@0 -35.82 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:31:05

20MHz_15kHz_3710MHz_DFT-s-OFDM QPSK_RB1@0 -35.40 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 19:27:48

20MHz_15kHz_3710MHz_DFT-s-OFDM QPSK_RB1@0 -47.19 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 19:27:32

20MHz_15kHz_3710MHz_DFT-s-OFDM QPSK_RB1@105 -47.32 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 19:28:41

20MHz_15kHz_3710MHz_DFT-s-OFDM QPSK_RB1@105 -35.34 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 19:28:58

20MHz_15kHz_3710MHz_DFT-s-OFDM QPSK_RB100@0 -34.87 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 20:25:09

20MHz_15kHz_3710MHz_DFT-s-OFDM QPSK_RB100@0 -47.04 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 19:29:49


20MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -35.21 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 19:34:52


20MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -46.96 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 19:34:34


20MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@105 -47.07 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 19:39:08


20MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB1@105 -35.75 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 19:39:47


20MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB100@0 -39.14 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng

Date: 22.MAY.2024 19:40:40


20MHz_15kHz_3840MHz_DFT-s-OFDM QPSK_RB100@0 -35.94 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng


Date: 22.MAY.2024 19:40:57

20MHz_15kHz_3970MHz_DFT-s-OFDM QPSK_RB1@0 -35.85 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 19:55:59

20MHz_15kHz_3970MHz_DFT-s-OFDM QPSK_RB1@0 -39.08 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 19:52:52

20MHz_15kHz_3970MHz_DFT-s-OFDM QPSK_RB1@105 -35.62 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 20:01:54

20MHz_15kHz_3970MHz_DFT-s-OFDM QPSK_RB1@105 -47.33 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 20:01:37

20MHz_15kHz_3970MHz_DFT-s-OFDM QPSK_RB100@0 -46.98 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 20:06:19

20MHz_15kHz_3970MHz_DFT-s-OFDM QPSK_RB100@0 -35.32 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 20:06:44

20MHz_30kHz_3710MHz_DFT-s-OFDM QPSK_RB1@0 -35.63 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:33:12

20MHz_30kHz_3710MHz_DFT-s-OFDM QPSK_RB1@0 -47.33 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:32:48

20MHz_30kHz_3710MHz_DFT-s-OFDM QPSK_RB1@50 -47.02 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:34:42

20MHz_30kHz_3710MHz_DFT-s-OFDM QPSK_RB1@50 -35.69 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:35:05

20MHz_30kHz_3710MHz_DFT-s-OFDM QPSK_RB50@0 -47.19 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:36:32

20MHz_30kHz_3710MHz_DFT-s-OFDM QPSK_RB50@0 -35.30 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:37:13

20MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -35.75 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:39:08

20MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@0 -46.77 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:38:46

20MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@50 -35.80 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:41:09

20MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB1@50 -47.48 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:40:33

20MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB50@0 -35.47 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:43:18

20MHz_30kHz_3840MHz_DFT-s-OFDM QPSK_RB50@0 -46.68 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 22.MAY.2024 21:42:32