


3. Internal Photograph of EUT

Applicant: Motorola Solutions, Inc. / Brand Name: Motorola /
Model Name: TLK 100 / Model Number: HK2112A / FCC ID: AZ489FT7117




Applicant: Motorola Solutions, Inc. / Brand Name: Motorola /
Model Name: TLK 100 / Model Number: HK2112A / FCC ID: AZ489FT7117




<Device disassembled battery cover>

Applicant: Motorola Solutions, Inc. / Brand Name: Motorola /
Model Name: TLK 100 / Model Number: HK2112A / FCC ID: AZ489FT7117




<Device disassembled rear housing>

Applicant: Motorola Solutions, Inc. / Brand Name: Motorola /
Model Name: TLK 100 / Model Number: HK2112A / FCC ID: AZ489FT7117




<Device disassembled main PCBA>

Applicant: Motorola Solutions, Inc. / Brand Name: Motorola /
Model Name: TLK 100 / Model Number: HK2112A / FCC ID: AZ489FT7117




<Main PCBA top side>

Applicant: Motorola Solutions, Inc. / Brand Name: Motorola /
Model Name: TLK 100 / Model Number: HK2112A / FCC ID: AZ489FT7117




<Main PCBA bottom side>

Applicant: Motorola Solutions, Inc. / Brand Name: Motorola /
Model Name: TLK 100 / Model Number: HK2112A / FCC ID: AZ489FT7117




<Device disassembled speaker frame>

Applicant: Motorola Solutions, Inc. / Brand Name: Motorola /
Model Name: TLK 100 / Model Number: HK2112A / FCC ID: AZ489FT7117




<Device disassembled display PCBA>

Applicant: Motorola Solutions, Inc. / Brand Name: Motorola /
Model Name: TLK 100 / Model Number: HK2112A / FCC ID: AZ489FT7117




<Display PCBA bottom side>

Applicant: Motorola Solutions, Inc. / Brand Name: Motorola /
Model Name: TLK 100 / Model Number: HK2112A / FCC ID: AZ489FT7117




<Display PCBA top side>

Applicant: Motorola Solutions, Inc. / Brand Name: Motorola /
Model Name: TLK 100 / Model Number: HK2112A / FCC ID: AZ489FT7117




<Device disassembled speaker_mic_USB_audiojack FPCA>

Applicant: Motorola Solutions, Inc. / Brand Name: Motorola /
Model Name: TLK 100 / Model Number: HK2112A / FCC ID: AZ489FT7117




<Speaker_mic_USB_audiojack FPCA top side>

Applicant: Motorola Solutions, Inc. / Brand Name: Motorola /
Model Name: TLK 100 / Model Number: HK2112A / FCC ID: AZ489FT7117




<Speaker_mic_USB_audiojack FPCA bottom side>

Applicant: Motorola Solutions, Inc. / Brand Name: Motorola /
Model Name: TLK 100 / Model Number: HK2112A / FCC ID: AZ489FT7117



<Device disassembled LTE diversity antenna>

Applicant: Motorola Solutions, Inc. / Brand Name: Motorola /
Model Name: TLK 100 / Model Number: HK2112A / FCC ID: AZ489FT7117




<Device disassembled GPS/WIFI/BT antenna frame>

Applicant: Motorola Solutions, Inc. / Brand Name: Motorola /
Model Name: TLK 100 / Model Number: HK2112A / FCC ID: AZ489FT7117




<Device disassembled LTE main antenna>

Applicant: Motorola Solutions, Inc. / Brand Name: Motorola /
Model Name: TLK 100 / Model Number: HK2112A / FCC ID: AZ489FT7117




<Main PCBA top side remove shielding can>

Applicant: Motorola Solutions, Inc. / Brand Name: Motorola /
Model Name: TLK 100 / Model Number: HK2112A / FCC ID: AZ489FT7117




<Main PCBA top side remove shielding frame>

Applicant: Motorola Solutions, Inc. / Brand Name: Motorola /
Model Name: TLK 100 / Model Number: HK2112A / FCC ID: AZ489FT7117




<Main PCBA bottom side remove shielding can>

Applicant: Motorola Solutions, Inc. / Brand Name: Motorola /
Model Name: TLK 100 / Model Number: HK2112A / FCC ID: AZ489FT7117




<Main PCBA bottom side remove shielding frame>

Applicant: Motorola Solutions, Inc. / Brand Name: Motorola /
Model Name: TLK 100 / Model Number: HK2112A / FCC ID: AZ489FT7117




<Display PCBA bottom side remove shielding can>

Applicant: Motorola Solutions, Inc. / Brand Name: Motorola /
Model Name: TLK 100 / Model Number: HK2112A / FCC ID: AZ489FT7117




<Display PCBA bottom side without shielding can>

Applicant: Motorola Solutions, Inc. / Brand Name: Motorola /
Model Name: TLK 100 / Model Number: HK2112A / FCC ID: AZ489FT7117




<Display PCBA top side remove rubber lampshade>

Applicant: Motorola Solutions, Inc. / Brand Name: Motorola /
Model Name: TLK 100 / Model Number: HK2112A / FCC ID: AZ489FT7117




<Display PCBA top side without rubber lampshade>

**Applicant: Motorola Solutions, Inc. / Brand Name: Motorola /
Model Name: TLK 100 / Model Number: HK2112A / FCC ID: AZ489FT7117**




<Main PCBA bottom side without shielding can>

Applicant: Motorola Solutions, Inc. / Brand Name: Motorola /
Model Name: TLK 100 / Model Number: HK2112A / FCC ID: AZ489FT7117




<Main PCBA bottom side without shielding can>

Applicant: Motorola Solutions, Inc. / Brand Name: Motorola /
Model Name: TLK 100 / Model Number: HK2112A / FCC ID: AZ489FT7117




<Main PCBA bottom side without shielding can>

Applicant: Motorola Solutions, Inc. / Brand Name: Motorola /
Model Name: TLK 100 / Model Number: HK2112A / FCC ID: AZ489FT7117




<Main PCBA bottom side without shielding can>

Applicant: Motorola Solutions, Inc. / Brand Name: Motorola /
Model Name: TLK 100 / Model Number: HK2112A / FCC ID: AZ489FT7117




<Main PCBA top side without shielding can>

Applicant: Motorola Solutions, Inc. / Brand Name: Motorola /
Model Name: TLK 100 / Model Number: HK2112A / FCC ID: AZ489FT7117




<Main PCBA top side without shielding can>

Applicant: Motorola Solutions, Inc. / Brand Name: Motorola /
Model Name: TLK 100 / Model Number: HK2112A / FCC ID: AZ489FT7117




<Main PCBA top side without shielding can>

Applicant: Motorola Solutions, Inc. / Brand Name: Motorola /
Model Name: TLK 100 / Model Number: HK2112A / FCC ID: AZ489FT7117




<Display PCBA bottom side without shielding can>


Applicant: Motorola Solutions, Inc. / Brand Name: Motorola /
Model Name: TLK 100 / Model Number: HK2112A / FCC ID: AZ489FT7117



Applicant: Motorola Solutions, Inc. / Brand Name: Motorola /
Model Name: TLK 100 / Model Number: HK2112A / FCC ID: AZ489FT7117



Applicant: Motorola Solutions, Inc. / Brand Name: Motorola /
Model Name: TLK 100 / Model Number: HK2112A / FCC ID: AZ489FT7117



Applicant: Motorola Solutions, Inc. / Brand Name: Motorola /
Model Name: TLK 100 / Model Number: HK2112A / FCC ID: AZ489FT7117

