



Tested By:Hong, Report No.:9904248

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10K	PR	20ms	AUTO	LN OFF	60dB


Final Measurement: X QF

Transducer No.	Start	Stop	Name
3	9k	30M	EI078

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB





Intertek Testing Services

ETL SEMKO

Report No.:9904248

Tested By:Hong, Report No.:9904248

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency MHz	QP Level dBuV	QP Limit dBuV
0.45500	27.8	48.0
0.59000	23.9	48.0
0.76500	20.2	48.0

* limit exceeded

Ctrl. No.: N/A