



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 10.MAR.2022 17:29:39

Band 2_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 10.MAR.2022 17:30:13

Band 2_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 10.MAR.2022 17:30:50

Band 2_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 10.MAR.2022 17:31:17

Band 2_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 10.MAR.2022 17:31:52

Band 2_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 10.MAR.2022 17:32:16

Band 2_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 10.MAR.2022 17:32:49

Band 2_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 10.MAR.2022 17:33:19

Band 2_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 10.MAR.2022 17:33:46

Band 2_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 10.MAR.2022 17:34:14

Band 2_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 10.MAR.2022 17:39:22

Band 2_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 10.MAR.2022 17:39:49

Band 2_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 10.MAR.2022 17:40:18

Band 2_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 10.MAR.2022 17:40:48

Band 2_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 10.MAR.2022 17:41:22

Band 2_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 10.MAR.2022 17:41:49

Band 2_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 10.MAR.2022 17:42:20

Band 2_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 10.MAR.2022 17:42:54

Band 2_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 10.MAR.2022 17:43:28

Band 2_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 10.MAR.2022 17:43:55

Band 2_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 10.MAR.2022 17:44:30

Band 2_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 10.MAR.2022 17:44:54

Band 2_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 10.MAR.2022 17:45:29

Band 2_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 10.MAR.2022 17:46:02

Band 2_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 10.MAR.2022 17:46:35

Band 2_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 10.MAR.2022 17:47:08

Band 2_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 10.MAR.2022 17:47:42

Band 2_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 10.MAR.2022 17:48:10

Band 2_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 10.MAR.2022 17:48:41

Band 2_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 10.MAR.2022 17:49:08

Band 2_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 10.MAR.2022 17:49:41

Band 2_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 10.MAR.2022 17:50:04

Band 2_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 10.MAR.2022 17:50:42

Band 2_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 10.MAR.2022 17:51:05

Band 2_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 10.MAR.2022 17:51:46

Band 2_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 10.MAR.2022 17:52:13

Band 4_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 10.MAR.2022 17:52:46

Band 4_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 10.MAR.2022 17:53:09

Band 4_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 10.MAR.2022 17:53:48

Band 4_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 10.MAR.2022 17:54:12

Band 4_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 10.MAR.2022 17:55:01

Band 4_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 10.MAR.2022 17:55:28

Band 4_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 10.MAR.2022 17:55:57

Band 4_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 10.MAR.2022 17:56:19

Band 4_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 10.MAR.2022 17:56:50

Band 4_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 10.MAR.2022 17:57:11

Band 4_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 10.MAR.2022 17:59:26

Band 4_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 10.MAR.2022 17:59:50

Band 4_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 10.MAR.2022 18:00:25

Band 4_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 10.MAR.2022 18:00:52

Band 4_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 10.MAR.2022 18:01:26

Band 4_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 10.MAR.2022 18:01:56

Band 4_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 10.MAR.2022 18:02:24

Band 4_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 10.MAR.2022 18:02:44

Band 4_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 10.MAR.2022 18:03:15

Band 4_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 10.MAR.2022 18:03:36

Band 4_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 10.MAR.2022 18:04:14

Band 4_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 10.MAR.2022 18:04:38

Band 4_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 10.MAR.2022 18:05:10

Band 4_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 10.MAR.2022 18:05:37

Band 4_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 10.MAR.2022 18:06:13

Band 4_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 10.MAR.2022 18:06:34

Band 4_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 10.MAR.2022 18:07:15

Band 4_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 10.MAR.2022 18:07:42

Band 4_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 10.MAR.2022 18:08:16

Band 4_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 10.MAR.2022 18:08:47

Band 4_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 10.MAR.2022 18:09:26

Band 4_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 10.MAR.2022 18:09:53

Band 4_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 11.MAR.2022 08:43:10

Band 4_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 11.MAR.2022 08:43:33

Band 4_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 11.MAR.2022 08:44:00

Band 4_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 11.MAR.2022 08:44:34

Band 5_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 29.MAR.2022 19:36:31

Band 5_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 29.MAR.2022 19:36:54

Band 5_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 29.MAR.2022 19:37:26

Band 5_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 29.MAR.2022 19:37:51

Band 5_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 29.MAR.2022 19:38:27

Band 5_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 29.MAR.2022 19:38:52

Band 5_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 29.MAR.2022 19:39:23

Band 5_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 29.MAR.2022 19:39:51

Band 5_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 29.MAR.2022 19:40:27

Band 5_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 29.MAR.2022 19:40:50

Band 5_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)



Date: 29.MAR.2022 19:41:13

Band 5_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)



Date: 29.MAR.2022 19:41:38