


EMC Technologies Report Number: M050422_Cert_WLL4070_11abg_DTS_BT

APPENDIX K1
Harmonics - Atheros 802.11a



Harmonics – Channel 149

Marker 1 [T1] RBW 100 kHz RF Att 30 dB
Ref Lvl -3.77 dBm VBW 300 kHz
15 dBm 5.68937876 GHz SWT 9.8 s Unit dBm




Date: 14.APR.2005 15:40:52




Harmonics - Channel 152

Marker 1 [T1] RBW 100 kHz RF Att 30 dB
Ref Lvl -2.53 dBm VBW 300 kHz
15 dBm 5.76753507 GHz SWT 9.8 s Unit dBm



Date: 14.APR.2005 16:11:51




Harmonics - Channel 157

Date: 14.APR.2005 15:49:25



Harmonics - Channel 160

Marker 1 [T1] RBW 100 kHz RF Att 30 dB
Ref Lvl -1.60 dBm VBW 300 kHz
15 dBm 5.76753507 GHz SWT 9.8 s Unit dBm




Date: 14.APR.2005 16:05:56



Harmonics - Channel 165

Marker 1 [T1] RBW 100 kHz RF Att 30 dB
Ref Lvl -1.66 dBm VBW 300 kHz
15 dBm 5.76753507 GHz SWT 9.8 s Unit dBm



Date: 14.APR.2005 15:57:27

