

Telecell Mobile (H.K) Co. Ltd.
RM 801 Metro Ctr 2, 21 Lam Hing Street Kln Bay, Hong Kong
Tel: +852-27599962 Fax: +852-27599711
regina@telecellmobile.com

Attestation Letter

2017-08-26

To:
Federal Communications Commission
Office of Engineering and Technology Laboratory Division
7435 Oakland Mills Road
Columbia MD 21046-1609
Phone: +1-301-362-3000
Fax: +1-301-362-3290

Dear Sir or Madam:

The RF chip, model SC7701B, installed in our product: Mobile Phone, model: Fury W242, FCC ID: 2ADX3W242. Which support HSDPA and HSUPA function, for using in the US market, it does not support HSDPA and HSUPA function. It have been shielded by the manufacture via using the software.

Best Regards,

Signature:



Regina Wong
Product Manager