

Steve Cheng

From: eric@ccsemc.com.tw
Sent: Wednesday, October 08, 2003 2:35 AM
To: scheng@ccsemc.com
Cc: lucy_tsai@ccsemc.com.tw; jonson@ccsemc.com.tw; miro@ccsemc.com.tw; mkuo@ccsemc.com; swang@ccsemc.com
Subject: Re: AN03T3296-PCE-ChiMei-QDJ-0307 TCB question

Hi, Steve,

For the Q1, please refer to the one attached this time. Which is the most updated and just received from our client at this moment. FYI, and please discard the one we have sent you before.

Thank you!!

BR, Eric

----- ? ? ? eric/ccsemc ? 2003/10/08 05:26 PM -----

eric
 ? ? ? ? ? : scheng@ccsemc.com
 ? ? ? ? ? : lucy_tsai/ccsemc@ccsemc, jonson/ccsemc@ccsemc, miro/ccsemc@ccsemc, mkuo@ccsemc.com,
 swang@ccsemc.com
 2003/10/08 10:50 AM ? ? : Re: AN03T3296-PCE-ChiMei-QDJ-0307 TCB question

Hi, Steve,

Please find the replies for the PCE as follows, prepared per the your comments.

PCE

1. Please refer to the revised tune up procedure attached.
2. Please refer to the revised POA attached.
3. Please refer to the revised test report attached.
4. Please refer to the revised user manual attached.
5. Please find the changes upon your comment on the revised Test report
6. The statement you'd requested is already shown on the report pg.6.

10/10/2003

7. Please find the changes on the revised SAR report.
8. Please find the changes upon your comment on the revised SAR report.

Replies for the DTS will be followed...

Thank you!!

Should you have any question, please don't hesitate to ask me.

Best regards,

Eric Wong

Compliance Certification Services Inc. (Formerly C&C Laboratory Co., Ltd.)

Tel.: +886-3-3240332 Ext.49

Add.: No.81-1, Lane 210, Ba-de 2nd Rd., Luchu Hsiang, Taoyuan Hsien 338, Taiwan, R.O.C.

Email: eric@ccsemc.com.tw

URL: <http://www.ccsemc.com.tw>

----- ? ? ? lucy_tsai/ccsemc ? 2003/10/06 09:16 AM -----

Steve Cheng <SCheng@CCSEMC.com>

? ? ? : "Lucy (E-mail)" <lucy_tsai@cclab.com.tw>, "Jonson (E-mail)" <jonson@cclab.com.tw>

2003/10/04 10:12 AM

? ? ? ? : Mike Kuo <MKUO@CCSEMC.com>, Scott Wang <SWang@CCSEMC.com>

? ? : Re: AN03T3296-PCE-ChiMei-QDJ-0307 TCB question

RT for project:

Question #1: Tune-up procedure does not has the required info, i.e. how to setup the required RF output power and spec. Please revise.

Question #2: Need to revise POA, it refers to old agent name.

Question #3: Test setup photos do not matching the DUT, please clarify.

Question #4: User manual p9 stated that "For body worn operation, this phone has been tested and meets the FCC RF exposure guidelines when used with an accessory that contains no metal and that position the antenna of the GSM phone a minimum of 1.5cm from the body. The SAR values of this GSM phone are 1.52mW/g (body) and 0.347mW/g (head). Use of other accessories may not ensure compliance with the FCC RF exposure guidelines." The specified SAR value is not consistent with measured vale in the SAR report. Please correct.

Question #5: EMC test report p22, Please explain if this device has GPRS 10 to 15 classe and how it work.

10/10/2003

Figure 7-6 GSM
Figure 7-7 GPRS (Class 10)
Figure 7-8 GPRS (Class 11)
Figure 7-9 GPRS (Class 12)
Figure 7-10 GPRS (Class 13)
Figure 7-11 GPRS (Class 14)
Figure 7-12 GPRS (Class 15)

Question #6: Please specify how DUT was set upped during the co-location test, i.e. which frequency GSM/GPRS was tuned to and what power level it outputted during the collocation test.

Question #7: Some of the critical info from the calibration file is necessary during the review process. Please supply the complete calibration record for CAE, Dipole and measurement Probe.

Question #8: SAR report p15 "IEEE P1528 Recommended Reference Value table" is not consistent with IEEE P1528 or FCC supplement C publishes value. And is not used in the test. Please explain how this related to the test.

Review will continue when requested data uploaded.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 60 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

Best Regards

Steve Cheng
Compliance Certification Services
561F Monterey Road
Morgan Hill, CA 95037
Tel:(408)463-0885 x:119
Fax:(408)463-0888
scheng@ccsemc.com
<http://www.ccsemc.com>

10/10/2003