


View only - use layout file for the laser etch machine.



1:1



4:1

METAL SHIELD
CONNECTION LINE

Use "JP ICON" as reference to get the right size.

Use layout file as input for the laser etch machine.

Don't laser etch in the in the connection line of the metal shield.

Cosmetic Standard: GSC.ST.00002
Part Marking.: GSC.PR.00102

CONFIDENTIALITY NOTICE:

This document is the property of GN Netcom A/S and must be treated as confidential. The document must not be used, or disclosed to any third party, without written permission by GN Netcom A/S. Copyright © 2010 GN Netcom A/S. All rights reserved.

Process control dimensions are marked:

IQC/OQC Characteristics for Evaluation:

--

Date of Change:

Description of Change:

Responsible:



Matr. Spec: (See B.O.M.)

3D revision:

Created by:

Created on:

Tool marking:

Drawing Scale:

Size:

Matr. type:

ECAI

13-Feb-2017

.....

2:1

A4

GN PDM file:

Object type: PART

Approved by:

Approved on:

Units:

Projection:

50-06747_REAR_HOUSING ver:J.1

Jayway H.

13-Feb-2017

mm



Description:

Document No:

Doc. Revision:

Design Status:

Page No:

Placement LASER ETCH, BOTTOM_LINK 370

50-07962

B

Released

1 of 1

A

B

C

D

E

F