



Plot on Configuration VHT80 / 5210 MHz / Average / Port 3 / 3GHz~6GHz




Date: 31.MAR.2018 17:51:01

Plot on Configuration VHT80 / 5210 MHz / Average / Port 4 / 3GHz~6GHz




Date: 31.MAR.2018 18:01:43

Plot on Configuration VHT80 / 5210 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 31.MAR.2018 17:08:07

Plot on Configuration VHT80 / 5210 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 31.MAR.2018 17:31:06

Plot on Configuration VHT80 / 5210 MHz / Peak / Port 3 / 3GHz~6GHz




Date: 31.MAR.2018 17:52:37

Plot on Configuration VHT80 / 5210 MHz / Peak / Port 4 / 3GHz~6GHz




Date: 31.MAR.2018 18:04:15

Plot on Configuration VHT20 / 5745 MHz / Average / Port 1 / 3GHz~6GHz




Date: 20.MAR.2018 19:44:50

Plot on Configuration VHT20 / 5745 MHz / Average / Port 2 / 3GHz~6GHz




Date: 20.MAR.2018 19:43:02

Plot on Configuration VHT20 / 5745 MHz / Average / Port 3 / 3GHz~6GHz




Date: 20.MAR.2018 19:42:03

Plot on Configuration VHT20 / 5745 MHz / Average / Port 4 / 3GHz~6GHz




Date: 20.MAR.2018 19:40:01

Plot on Configuration VHT20 / 5745 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 20.MAR.2018 19:44:15

Plot on Configuration VHT20 / 5745 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 20.MAR.2018 19:43:27

Plot on Configuration VHT20 / 5745 MHz / Peak / Port 3 / 3GHz~6GHz




Date: 20.MAR.2018 19:41:27

Plot on Configuration VHT20 / 5745 MHz / Peak / Port 4 / 3GHz~6GHz




Date: 20.MAR.2018 19:40:42

Plot on Configuration VHT20 / 5785 MHz / Average / Port 1 / 3GHz~6GHz




Date: 20.MAR.2018 19:46:29

Plot on Configuration VHT20 / 5785 MHz / Average / Port 2 / 3GHz~6GHz




Date: 20.MAR.2018 19:48:28

Plot on Configuration VHT20 / 5785 MHz / Average / Port 3 / 3GHz~6GHz




Date: 20.MAR.2018 19:49:24

Plot on Configuration VHT20 / 5785 MHz / Average / Port 4 / 3GHz~6GHz




Date: 20.MAR.2018 19:51:08

Plot on Configuration VHT20 / 5785 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 20.MAR.2018 19:47:07

Plot on Configuration VHT20 / 5785 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 20.MAR.2018 19:47:58

Plot on Configuration VHT20 / 5785 MHz / Peak / Port 3 / 3GHz~6GHz




Date: 20.MAR.2018 19:49:57

Plot on Configuration VHT20 / 5785 MHz / Peak / Port 4 / 3GHz~6GHz




Date: 20.MAR.2018 19:50:36


Plot on Configuration VHT20 / 5825 MHz / Average / Port 1 / 3GHz~6GHz



Plot on Configuration VHT20 / 5825 MHz / Average / Port 2 / 3GHz~6GHz




Plot on Configuration VHT20 / 5825 MHz / Average / Port 3 / 3GHz~6GHz




Date: 20.MAR.2018 19:33:43

Plot on Configuration VHT20 / 5825 MHz / Average / Port 4 / 3GHz~6GHz




Date: 20.MAR.2018 19:35:10

Plot on Configuration VHT20 / 5825 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 20.MAR.2018 19:31:54

Plot on Configuration VHT20 / 5825 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 20.MAR.2018 19:31:34

Plot on Configuration VHT20 / 5825 MHz / Peak / Port 3 / 3GHz~6GHz




Date: 20.MAR.2018 19:34:02

Plot on Configuration VHT20 / 5825 MHz / Peak / Port 4 / 3GHz~6GHz




Date: 20.MAR.2018 19:34:31

Plot on Configuration VHT40 / 5755 MHz / Average / Port 1 / 3GHz~6GHz




Date: 20.MAR.2018 19:57:04

Plot on Configuration VHT40 / 5755 MHz / Average / Port 2 / 3GHz~6GHz




Date: 20.MAR.2018 19:55:03


Plot on Configuration VHT40 / 5755 MHz / Average / Port 3 / 3GHz~6GHz



Plot on Configuration VHT40 / 5755 MHz / Average / Port 4 / 3GHz~6GHz




Plot on Configuration VHT40 / 5755 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 20.MAR.2018 19:57:41

Plot on Configuration VHT40 / 5755 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 20.MAR.2018 19:55:37

Plot on Configuration VHT40 / 5755 MHz / Peak / Port 3 / 3GHz~6GHz




Date: 20.MAR.2018 19:54:04

Plot on Configuration VHT40 / 5755 MHz / Peak / Port 4 / 3GHz~6GHz




Date: 20.MAR.2018 19:53:31

Plot on Configuration VHT40 / 5795 MHz / Average / Port 1 / 3GHz~6GHz




Date: 20.MAR.2018 20:00:32

Plot on Configuration VHT40 / 5795 MHz / Average / Port 2 / 3GHz~6GHz




Date: 20.MAR.2018 20:01:45

Plot on Configuration VHT40 / 5795 MHz / Average / Port 3 / 3GHz~6GHz




Date: 20.MAR.2018 20:03:28

Plot on Configuration VHT40 / 5795 MHz / Average / Port 4 / 3GHz~6GHz




Date: 20.MAR.2018 20:04:15

Plot on Configuration VHT40 / 5795 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 20.MAR.2018 19:59:58

Plot on Configuration VHT40 / 5795 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 20.MAR.2018 20:02:09


Plot on Configuration VHT40 / 5795 MHz / Peak / Port 3 / 3GHz~6GHz



Plot on Configuration VHT40 / 5795 MHz / Peak / Port 4 / 3GHz~6GHz




Plot on Configuration VHT80 / 5775 MHz / Average / Port 1 / 3GHz~6GHz




Date: 20.MAR.2018 20:13:50

Plot on Configuration VHT80 / 5775 MHz / Average / Port 2 / 3GHz~6GHz




Date: 20.MAR.2018 20:11:58

Plot on Configuration VHT80 / 5775 MHz / Average / Port 3 / 3GHz~6GHz




Date: 20.MAR.2018 20:09:16

Plot on Configuration VHT80 / 5775 MHz / Average / Port 4 / 3GHz~6GHz




Date: 20.MAR.2018 20:08:30

Plot on Configuration VHT80 / 5775 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 20.MAR.2018 20:13:17

Plot on Configuration VHT80 / 5775 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 20.MAR.2018 20:10:31

Plot on Configuration VHT80 / 5775 MHz / Peak / Port 3 / 3GHz~6GHz




Date: 20.MAR.2018 20:09:52

Plot on Configuration VHT80 / 5775 MHz / Peak / Port 4 / 3GHz~6GHz




Date: 20.MAR.2018 20:07:55

Plot on Configuration VHT20 / 5180 MHz / Average / Port 1 / 6GHz~9GHz




Date: 30.MAR.2018 16:04:21

Plot on Configuration VHT20 / 5180 MHz / Average / Port 2 / 6GHz~9GHz




Date: 30.MAR.2018 16:07:39

Plot on Configuration VHT20 / 5180 MHz / Average / Port 3 / 6GHz~9GHz




Date: 30.MAR.2018 16:15:40

Plot on Configuration VHT20 / 5180 MHz / Average / Port 4 / 6GHz~9GHz




Date: 30.MAR.2018 16:19:14

Plot on Configuration VHT20 / 5180 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 30.MAR.2018 16:05:36

Plot on Configuration VHT20 / 5180 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 30.MAR.2018 16:08:29

Plot on Configuration VHT20 / 5180 MHz / Peak / Port 3 / 6GHz~9GHz




Date: 30.MAR.2018 16:16:40

Plot on Configuration VHT20 / 5180 MHz / Peak / Port 4 / 6GHz~9GHz




Date: 30.MAR.2018 16:20:06

Plot on Configuration VHT20 / 5200 MHz / Average / Port 1 / 6GHz~9GHz




Date: 30.MAR.2018 16:33:56

Plot on Configuration VHT20 / 5200 MHz / Average / Port 2 / 6GHz~9GHz




Date: 30.MAR.2018 16:36:52

Plot on Configuration VHT20 / 5200 MHz / Average / Port 3 / 6GHz~9GHz




Date: 30.MAR.2018 16:47:57

Plot on Configuration VHT20 / 5200 MHz / Average / Port 4 / 6GHz~9GHz




Date: 30.MAR.2018 16:51:11

Plot on Configuration VHT20 / 5200 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 30.MAR.2018 16:34:38

Plot on Configuration VHT20 / 5200 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 30.MAR.2018 16:37:43

Plot on Configuration VHT20 / 5200 MHz / Peak / Port 3 / 6GHz~9GHz




Date: 30.MAR.2018 16:48:47

Plot on Configuration VHT20 / 5200 MHz / Peak / Port 4 / 6GHz~9GHz




Date: 30.MAR.2018 16:52:06

Plot on Configuration VHT20 / 5240 MHz / Average / Port 1 / 6GHz~9GHz




Date: 30.MAR.2018 17:18:35

Plot on Configuration VHT20 / 5240 MHz / Average / Port 2 / 6GHz~9GHz




Date: 30.MAR.2018 17:24:56

Plot on Configuration VHT20 / 5240 MHz / Average / Port 3 / 6GHz~9GHz




Date: 30.MAR.2018 17:48:19

Plot on Configuration VHT20 / 5240 MHz / Average / Port 4 / 6GHz~9GHz




Date: 30.MAR.2018 17:53:07

Plot on Configuration VHT20 / 5240 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 30.MAR.2018 17:19:41


Plot on Configuration VHT20 / 5240 MHz / Peak / Port 2 / 6GHz~9GHz



Date: 30.MAR.2018 17:27:56




Plot on Configuration VHT20 / 5240 MHz / Peak / Port 3 / 6GHz~9GHz




Date: 30.MAR.2018 17:50:32

Plot on Configuration VHT20 / 5240 MHz / Peak / Port 4 / 6GHz~9GHz




Date: 30.MAR.2018 17:54:05

Plot on Configuration VHT40 / 5190 MHz / Average / Port 1 / 6GHz~9GHz




Date: 31.MAR.2018 15:24:17

Plot on Configuration VHT40 / 5190 MHz / Average / Port 2 / 6GHz~9GHz




Date: 31.MAR.2018 15:44:02

Plot on Configuration VHT40 / 5190 MHz / Average / Port 3 / 6GHz~9GHz




Date: 31.MAR.2018 15:40:39

Plot on Configuration VHT40 / 5190 MHz / Average / Port 4 / 6GHz~9GHz




Date: 31.MAR.2018 15:46:47

Plot on Configuration VHT40 / 5190 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 31.MAR.2018 15:25:13


Plot on Configuration VHT40 / 5190 MHz / Peak / Port 2 / 6GHz~9GHz



Date: 31.MAR.2018 15:44:50




Plot on Configuration VHT40 / 51980 MHz / Peak / Port 3 / 6GHz~9GHz




Date: 31.MAR.2018 15:42:01

Plot on Configuration VHT40 / 5190 MHz / Peak / Port 4 / 6GHz~9GHz




Date: 31.MAR.2018 15:47:32

Plot on Configuration VHT40 / 5230 MHz / Average / Port 1 / 6GHz~9GHz




Date: 31.MAR.2018 16:10:03

Plot on Configuration VHT40 / 5230 MHz / Average / Port 2 / 6GHz~9GHz




Date: 31.MAR.2018 16:14:04

Plot on Configuration VHT40 / 5230 MHz / Average / Port 3 / 6GHz~9GHz




Date: 31.MAR.2018 16:29:55

Plot on Configuration VHT40 / 5230 MHz / Average / Port 4 / 6GHz~9GHz




Date: 31.MAR.2018 16:39:21

Plot on Configuration VHT40 / 5230 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 31.MAR.2018 16:11:23


Plot on Configuration VHT40 / 5230 MHz / Peak / Port 2 / 6GHz~9GHz



Date: 31.MAR.2018 16:14:49




Plot on Configuration VHT40 / 5230 MHz / Peak / Port 3 / 6GHz~9GHz




Date: 31.MAR.2018 16:30:51

Plot on Configuration VHT40 / 5230 MHz / Peak / Port 4 / 6GHz~9GHz




Date: 31.MAR.2018 16:40:49

Plot on Configuration VHT80 / 5210 MHz / Average / Port 1 / 6GHz~9GHz




Date: 31.MAR.2018 17:10:02

Plot on Configuration VHT80 / 5210 MHz / Average / Port 2 / 6GHz~9GHz




Date: 31.MAR.2018 17:25:27

Plot on Configuration VHT80 / 5210 MHz / Average / Port 3 / 6GHz~9GHz




Date: 31.MAR.2018 17:54:10

Plot on Configuration VHT80 / 5210 MHz / Average / Port 4 / 6GHz~9GHz




Date: 31.MAR.2018 17:58:09

Plot on Configuration VHT80 / 5210 MHz / Peak / Port 1 / 6GHz~9GHz



Date: 31.MAR.2018 17:11:19


Plot on Configuration VHT80 / 5210 MHz / Peak / Port 2 / 6GHz~9GHz



Date: 31.MAR.2018 17:27:25




Plot on Configuration VHT80 / 5210 MHz / Peak / Port 3 / 6GHz~9GHz




Date: 31.MAR.2018 17:55:32

Plot on Configuration VHT80 / 5210 MHz / Peak / Port 4 / 6GHz~9GHz




Date: 31.MAR.2018 17:59:00

Plot on Configuration VHT20 / 5745 MHz / Average / Port 1 / 6GHz~9GHz




Date: 20.MAR.2018 20:16:29

Plot on Configuration VHT20 / 5745 MHz / Average / Port 2 / 6GHz~9GHz




Date: 20.MAR.2018 20:17:28

Plot on Configuration VHT20 / 5745 MHz / Average / Port 3 / 6GHz~9GHz




Date: 20.MAR.2018 20:17:58

Plot on Configuration VHT20 / 5745 MHz / Average / Port 4 / 6GHz~9GHz




Date: 20.MAR.2018 20:19:03

Plot on Configuration VHT20 / 5745 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 20.MAR.2018 20:16:45

Plot on Configuration VHT20 / 5745 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 20.MAR.2018 20:17:06

Plot on Configuration VHT20 / 5745 MHz / Peak / Port 3 / 6GHz~9GHz




Date: 20.MAR.2018 20:18:16

Plot on Configuration VHT20 / 5745 MHz / Peak / Port 4 / 6GHz~9GHz




Date: 20.MAR.2018 20:18:40

Plot on Configuration VHT20 / 5785 MHz / Average / Port 1 / 6GHz~9GHz




Date: 20.MAR.2018 20:23:18

Plot on Configuration VHT20 / 5785 MHz / Average / Port 2 / 6GHz~9GHz




Date: 20.MAR.2018 20:22:16

Plot on Configuration VHT20 / 5785 MHz / Average / Port 3 / 6GHz~9GHz




Date: 20.MAR.2018 20:21:46

Plot on Configuration VHT20 / 5785 MHz / Average / Port 4 / 6GHz~9GHz




Date: 20.MAR.2018 20:20:45

Plot on Configuration VHT20 / 5785 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 20.MAR.2018 20:22:55

Plot on Configuration VHT20 / 5785 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 20.MAR.2018 20:22:30

Plot on Configuration VHT20 / 5785 MHz / Peak / Port 3 / 6GHz~9GHz




Date: 20.MAR.2018 20:21:21

Plot on Configuration VHT20 / 5785 MHz / Peak / Port 4 / 6GHz~9GHz




Date: 20.MAR.2018 20:21:00

Plot on Configuration VHT20 / 5825 MHz / Average / Port 1 / 6GHz~9GHz




Date: 20.MAR.2018 20:25:32

Plot on Configuration VHT20 / 5825 MHz / Average / Port 2 / 6GHz~9GHz




Date: 20.MAR.2018 20:26:40

Plot on Configuration VHT20 / 5825 MHz / Average / Port 3 / 6GHz~9GHz




Date: 20.MAR.2018 20:27:16

Plot on Configuration VHT20 / 5825 MHz / Average / Port 4 / 6GHz~9GHz




Date: 20.MAR.2018 20:28:34

Plot on Configuration VHT20 / 5825 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 20.MAR.2018 20:25:48

Plot on Configuration VHT20 / 5825 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 20.MAR.2018 20:26:10

Plot on Configuration VHT20 / 5825 MHz / Peak / Port 3 / 6GHz~9GHz




Date: 20.MAR.2018 20:27:35

Plot on Configuration VHT20 / 5825 MHz / Peak / Port 4 / 6GHz~9GHz




Date: 20.MAR.2018 20:28:03


Plot on Configuration VHT40 / 5755 MHz / Average / Port 1 / 6GHz~9GHz



Plot on Configuration VHT40 / 5755 MHz / Average / Port 2 / 6GHz~9GHz




Plot on Configuration VHT40 / 5755 MHz / Average / Port 3 / 6GHz~9GHz




Date: 20.MAR.2018 20:32:20

Plot on Configuration VHT40 / 5755 MHz / Average / Port 4 / 6GHz~9GHz




Date: 20.MAR.2018 20:30:44

Plot on Configuration VHT40 / 5755 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 20.MAR.2018 20:33:34

Plot on Configuration VHT40 / 5755 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 20.MAR.2018 20:33:11

Plot on Configuration VHT40 / 5755 MHz / Peak / Port 3 / 6GHz~9GHz




Date: 20.MAR.2018 20:31:30

Plot on Configuration VHT40 / 5755 MHz / Peak / Port 4 / 6GHz~9GHz




Date: 20.MAR.2018 20:31:08

Plot on Configuration VHT40 / 5795 MHz / Average / Port 1 / 6GHz~9GHz




Date: 20.MAR.2018 20:36:33

Plot on Configuration VHT40 / 5795 MHz / Average / Port 2 / 6GHz~9GHz




Date: 20.MAR.2018 20:37:36

Plot on Configuration VHT40 / 5795 MHz / Average / Port 3 / 6GHz~9GHz




Date: 20.MAR.2018 20:38:06

Plot on Configuration VHT40 / 5795 MHz / Average / Port 4 / 6GHz~9GHz




Date: 20.MAR.2018 20:39:13

Plot on Configuration VHT40 / 5795 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 20.MAR.2018 20:36:47

Plot on Configuration VHT40 / 5795 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 20.MAR.2018 20:37:10

Plot on Configuration VHT40 / 5795 MHz / Peak / Port 3 / 6GHz~9GHz




Date: 20.MAR.2018 20:38:25

Plot on Configuration VHT40 / 5795 MHz / Peak / Port 4 / 6GHz~9GHz




Date: 20.MAR.2018 20:38:50

Plot on Configuration VHT80 / 5775 MHz / Average / Port 1 / 6GHz~9GHz




Date: 20.MAR.2018 20:44:08

Plot on Configuration VHT80 / 5775 MHz / Average / Port 2 / 6GHz~9GHz




Date: 20.MAR.2018 20:42:57


Plot on Configuration VHT80 / 5775 MHz / Average / Port 3 / 6GHz~9GHz



Plot on Configuration VHT80 / 5775 MHz / Average / Port 4 / 6GHz~9GHz




Plot on Configuration VHT80 / 5775 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 20.MAR.2018 20:43:40

Plot on Configuration VHT80 / 5775 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 20.MAR.2018 20:43:18

Plot on Configuration VHT80 / 5775 MHz / Peak / Port 3 / 6GHz~9GHz




Date: 20.MAR.2018 20:42:05

Plot on Configuration VHT80 / 5775 MHz / Peak / Port 4 / 6GHz~9GHz




Date: 20.MAR.2018 20:41:44

Plot on Configuration VHT20 / 5180 MHz / Average / Port 1 / 9GHz~18GHz




Date: 31.MAR.2018 18:22:31

Plot on Configuration VHT20 / 5180 MHz / Average / Port 2 / 9GHz~18GHz




Date: 31.MAR.2018 18:32:47

Plot on Configuration VHT20 / 5180 MHz / Average / Port 3 / 9GHz~18GHz




Date: 31.MAR.2018 18:35:45

Plot on Configuration VHT20 / 5180 MHz / Average / Port 4 / 9GHz~18GHz




Date: 31.MAR.2018 18:45:09

Plot on Configuration VHT20 / 5180 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 31.MAR.2018 18:23:25

Plot on Configuration VHT20 / 5180 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 31.MAR.2018 18:33:43

Plot on Configuration VHT20 / 5180 MHz / Peak / Port 3 / 9GHz~18GHz




Date: 31.MAR.2018 18:36:42

Plot on Configuration VHT20 / 5180 MHz / Peak / Port 4 / 9GHz~18GHz




Date: 31.MAR.2018 18:46:01

Plot on Configuration VHT20 / 5200 MHz / Average / Port 1 / 9GHz~18GHz




Date: 31.MAR.2018 18:53:05

Plot on Configuration VHT20 / 5200 MHz / Average / Port 2 / 9GHz~18GHz




Date: 31.MAR.2018 19:04:42

Plot on Configuration VHT20 / 5200 MHz / Average / Port 3 / 9GHz~18GHz




Date: 31.MAR.2018 19:08:03

Plot on Configuration VHT20 / 5200 MHz / Average / Port 4 / 9GHz~18GHz




Date: 31.MAR.2018 19:19:14

Plot on Configuration VHT20 / 5200 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 31.MAR.2018 18:54:06

Plot on Configuration VHT20 / 5200 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 31.MAR.2018 19:05:46

Plot on Configuration VHT20 / 5200 MHz / Peak / Port 3 / 9GHz~18GHz




Date: 31.MAR.2018 19:08:53

Plot on Configuration VHT20 / 5200 MHz / Peak / Port 4 / 9GHz~18GHz




Date: 31.MAR.2018 19:20:12

Plot on Configuration VHT20 / 5240 MHz / Average / Port 1 / 9GHz~18GHz




Date: 31.MAR.2018 19:24:42

Plot on Configuration VHT20 / 5240 MHz / Average / Port 2 / 9GHz~18GHz




Date: 31.MAR.2018 19:35:40

Plot on Configuration VHT20 / 5240 MHz / Average / Port 3 / 9GHz~18GHz




Date: 31.MAR.2018 19:40:39

Plot on Configuration VHT20 / 5240 MHz / Average / Port 4 / 9GHz~18GHz




Date: 31.MAR.2018 19:52:34

Plot on Configuration VHT20 / 5240 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 31.MAR.2018 19:25:53

Plot on Configuration VHT20 / 5240 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 31.MAR.2018 19:37:32

Plot on Configuration VHT20 / 5240 MHz / Peak / Port 3 / 9GHz~18GHz




Date: 31.MAR.2018 19:41:44

Plot on Configuration VHT20 / 5240 MHz / Peak / Port 4 / 9GHz~18GHz




Date: 31.MAR.2018 19:53:55

Plot on Configuration VHT40 / 5190 MHz / Average / Port 1 / 9GHz~18GHz




Date: 31.MAR.2018 20:01:31

Plot on Configuration VHT40 / 5190 MHz / Average / Port 2 / 9GHz~18GHz




Date: 31.MAR.2018 20:14:31

Plot on Configuration VHT40 / 5190 MHz / Average / Port 3 / 9GHz~18GHz




Date: 31.MAR.2018 20:18:48

Plot on Configuration VHT40 / 5190 MHz / Average / Port 4 / 9GHz~18GHz




Date: 31.MAR.2018 20:29:15

Plot on Configuration VHT40 / 5190 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 31.MAR.2018 20:03:03

Plot on Configuration VHT40 / 5190 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 31.MAR.2018 20:15:20

Plot on Configuration VHT40 / 5190 MHz / Peak / Port 3 / 9GHz~18GHz




Date: 31.MAR.2018 20:19:52

Plot on Configuration VHT40 / 5190 MHz / Peak / Port 4 / 9GHz~18GHz




Date: 31.MAR.2018 20:30:18

Plot on Configuration VHT40 / 5230 MHz / Average / Port 1 / 9GHz~18GHz




Date: 31.MAR.2018 20:55:28

Plot on Configuration VHT40 / 5230 MHz / Average / Port 2 / 9GHz~18GHz




Date: 31.MAR.2018 21:05:52

Plot on Configuration VHT40 / 5230 MHz / Average / Port 3 / 9GHz~18GHz




Date: 31.MAR.2018 21:09:50

Plot on Configuration VHT40 / 5230 MHz / Average / Port 4 / 9GHz~18GHz




Date: 31.MAR.2018 21:21:21


Plot on Configuration VHT40 / 5230 MHz / Peak / Port 1 / 9GHz~18GHz



Plot on Configuration VHT40 / 5230 MHz / Peak / Port 2 / 9GHz~18GHz




Plot on Configuration VHT40 / 5230 MHz / Peak / Port 3 / 9GHz~18GHz




Date: 31.MAR.2018 21:10:35

Plot on Configuration VHT40 / 5230 MHz / Peak / Port 4 / 9GHz~18GHz




Date: 31.MAR.2018 21:23:10

Plot on Configuration VHT80 / 5210 MHz / Average / Port 1 / 9GHz~18GHz




Date: 31.MAR.2018 21:28:02

Plot on Configuration VHT80 / 5210 MHz / Average / Port 2 / 9GHz~18GHz




Date: 31.MAR.2018 21:39:10


Plot on Configuration VHT80 / 5210 MHz / Average / Port 3 / 9GHz~18GHz



Plot on Configuration VHT80 / 5210 MHz / Average / Port 4 / 9GHz~18GHz




Plot on Configuration VHT80 / 5210 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 31.MAR.2018 21:29:01

Plot on Configuration VHT80 / 5210 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 31.MAR.2018 21:40:11

Plot on Configuration VHT80 / 5210 MHz / Peak / Port 3 / 9GHz~18GHz




Date: 31.MAR.2018 21:46:54

Plot on Configuration VHT80 / 5210 MHz / Peak / Port 4 / 9GHz~18GHz




Date: 31.MAR.2018 22:05:53

Plot on Configuration VHT20 / 5745 MHz / Average / Port 1 / 9GHz~18GHz



Date: 21.MAR.2018 10:51:32

Plot on Configuration VHT20 / 5745 MHz / Average / Port 2 / 9GHz~18GHz



Date: 21.MAR.2018 10:53:31