



American Telecommunications Certification Body Inc.  
6731 Whittier Ave, McLean, VA 22101

June 14, 2002

RE: Behavior Tech Computer Corporation

FCC ID: E5XKB2001URF

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) Please provide a photograph that shows where the antenna is located within this device and where it attaches to the board.
- 2) Is there a schematic available for the TX board or is this an OEM part. If it is an OEM part, please provide a parts list that shows this, if not then please provide the schematic for it.
- 3) If a parts list is to be provided, please let us know if confidentiality is requested on it, and update the confidentiality letter as necessary.

Timothy R. Johnson  
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.