


FCC ID and IC ID LABEL AND LOCATION

LABEL

RPT System Compliance labels



Battery Warning

WARNING

Risk of Fire, Explosion, and Electric Shock. Replace battery with EEMB Co. Ltd., model LP584374F-2S (Hunter part number 899400).

Use of a different battery has the potential risk of Fire, Explosion, and Electric Shock. See owner's manual for instructions.

— Cyan outlines = die line

FCC Label
Location/Affixation

Back of EUT

Label is a laminated
sticker label affixed
using adhesive.

