



### -6dB Bandwidth NVNT n20 5785MHz Ant1

-6dB Bandwidth NVNT n20 5825MHz Ant1




**Blue Asia** of Technical Services (Shenzhen) Co., Ltd. Tel: +86-755-23059481 Email: marketing@cblueasia.com www.cblueasia.com





## -6dB Bandwidth NVNT n40 5755MHz Ant1

-6dB Bandwidth NVNT n40 5795MHz Ant1




Blue Asia of Technical Services (Shenzhen) Co., Ltd. Tel: +86-755-23059481 Email: marketing@cblueasia.com www.cblueasia.com



Page 223 of 225

# Appendix B: photographs of test setup






Blue Asia of Technical Services (Shenzhen) Co., Ltd. Tel: +86-755-23059481 Email: marketing@cblueasia.com www.cblueasia.com



## Report No.: BLA-EMC-202503-A2703

Page 224 of 225



Blue Asia of technical Services (Shenzhen) Co., Ltd. Tel: +86-755-23059481

Email: <u>marketing@cblueasia.com</u> www.cblueasia.com



# Appendix C: photographs of EUT

Reference to the test report no. BLA-EMC-202503-A2701

#### ----END OF REPORT----

The test report is effective only with both signature and specialized stamp, the result(s) shown in this report refer only to the sample(s) tested. Without written approval of BlueAsia, this report can't be reproduced except in full.

Blue Asia of technical Services (Shenzhen) Co., Ltd.