

## TEST SETUP PHOTOS

### 1 Radiated Field Strength Measurement


Below 1 GHz



Close-up Photo




Above 1 GHz




Below 1 GHz, The USB Test Mode



Close-up Photo, The USB Test Mode



Above 1 GHz, The USB Test Mode



## 2 Conducted Emission



## The USB Test Mode



## The USB Test Mode

