

## INTERTEK TESTING SERVICES

---

### The Worst Case Configuration Photographs



Figure 1 – Front with 25mm Separation



Figure 2 – Front with 25mm Separation (antenna extended)

## INTERTEK TESTING SERVICES

---

### The Worst Case Configuration Photographs



Figure 3 – Front with 0mm Separation



Figure 4 – Back with 0mm Separation

## INTERTEK TESTING SERVICES

---

### The Worst Case Configuration Photographs




Figure 5 – Top with 0mm Separation




Figure 6 – Front with 0mm Separation (antenna extended)

## INTERTEK TESTING SERVICES

### The Worst Case Configuration Photographs




Figure 7 – Back with 0mm Separation (antenna extended)




Figure 8 – Top with 0mm Separation (antenna extended)