



Product	Module		
Test Item	Spurious Emissions at Antenna Terminals		
Test Mode	Mode 5: LTE Band 13		
Date of Test	2019/12/19	Test Site	SR12-H
Temperature (°C)	21.0°C	Humidity (%RH)	60%RH

B13_CH23205_5M_QPSK_1RB0_150k



Date: 19.DEC.2019 16:39:17

B13_CH23205_5M_QPSK_1RB0_15k




Date: 19.DEC.2019 16:38:30

B13_CH23205_5M_QPSK_25RB0_150k




Date: 19.DEC.2019 16:45:29

B13_CH23205_5M_QPSK_25RB0_15k




Date: 19.DEC.2019 16:46:08

B13_CH23205_5M_16-QAM_1RB0_150k



Date: 19.DEC.2019 17:14:17

B13_CH23205_5M_16-QAM_1RB0_15k




Date: 19.DEC.2019 17:13:38

B13_CH23205_5M_16-QAM_25RB0_150k




Date: 19.DEC.2019 17:15:59

B13_CH23205_5M_16-QAM_25RB0_15k




Date: 19.DEC.2019 17:16:28

B13_CH23255_5M_QPSK_1RB24_150k




Date: 19.DEC.2019 17:25:59

B13_CH23255_5M_QPSK_1RB24_15k




Date: 19.DEC.2019 17:27:49

LTE_B13_CH23255_5M_QPSK_25RB0_150k




Date: 19.DEC.2019 17:30:25

B13_CH23255_5M_QPSK_25RB0_15k




Date: 19.DEC.2019 17:28:55

B13_CH23255_5M_16-QAM_1RB24_150k




Date: 19.DEC.2019 17:22:58

B13_CH23255_5M_16-QAM_1RB24_15k




Date: 19.DEC.2019 17:22:29

B13_CH23255_5M_16-QAM_25RB0_150k




Date: 19.DEC.2019 17:19:16

B13_CH23255_5M_16-QAM_25RB0_15k




Date: 19.DEC.2019 17:20:08

B13_CH23230_10M_QPSK_1RB0_150k




Date: 19.DEC.2019 16:50:09

B13_CH23230_10M_QPSK_1RB0_15k




Date: 19.DEC.2019 16:51:56

B13_CH23230_10M_QPSK_50RB0_150k




Date: 19.DEC.2019 16:55:44

B13_CH23230_10M_QPSK_50RB0_15k




Date: 19.DEC.2019 16:56:27

B13_CH23230_10M_QPSK_1RB49_150k




Date: 19.DEC.2019 17:36:33

B13_CH23230_10M_QPSK_1RB49_15k




Date: 19.DEC.2019 17:37:10

B13_CH23230_10M_QPSK_50RB0_150k




Date: 19.DEC.2019 17:50:28

B13_CH23230_10M_QPSK_50RB0_15k




Date: 19.DEC.2019 17:45:23

B13_CH23230_10M_16-QAM__1RB0_150k




Date: 19.DEC.2019 17:07:18

B13_CH23230_10M_16-QAM__1RB0_15k




Date: 19.DEC.2019 17:10:03

B13_CH23230_10M_16-QAM__50RB0_150k




Date: 19.DEC.2019 17:02:25

B13_CH23230_10M_16-QAM__50RB0_15k




Date: 19.DEC.2019 17:01:45

B13_CH23230_10M_16-QAM_1RB49_150k




Date: 19, DEC, 2019 18:01:52

B13_CH23230_10M_16-QAM_1RB49_15k




Date: 19, DEC, 2019 18:01:08

B13_CH23230_10M_16-QAM_50RB0_150k



Date: 19.DEC.2019 17:55:31


B13_CH23230_10M_16-QAM_50RB0_15k



Date: 19.DEC.2019 17:58:06


Product	Module		
Test Item	Spurious Emissions at Antenna Terminals		
Test Mode	Mode 6: LTE Band 25		
Date of Test	2019/12/16~2019/12/17	Test Site	SR12-H
Temperature (°C)	22.0°C	Humidity (%RH)	60%RH

LTE_B25_CH26047_1.4M_QPSK_1RB0




Date: 16 DEC. 2019 18:57:57

LTE_B25_CH26047_1.4M_QPSK_6RB0




Date: 16 DEC. 2019 19:21:13


LTE_B25_CH26047_1.4M_16-QAM_1RB0



LTE_B25_CH26047_1.4M_16-QAM_6RB0




LTE_B25_CH26683_1.4M_QPSK_1RB5




Date: 16.DEC.2019 19:25:48

LTE_B25_CH26683_1.4M_QPSK_6RB0




Date: 16.DEC.2019 19:23:25

LTE_B25_CH26683_1.4M_16-QAM_1RB5




Date: 16.DEC.2019 19:25:29

LTE_B25_CH26683_1.4M_16-QAM_6RB0




Date: 16.DEC.2019 19:23:54

LTE_B25_CH26055_3M_QPSK_1RB0




Date: 16.DEC.2019 20:16:18

LTE_B25_CH26055_3M_QPSK_15RB0




Date: 16.DEC.2019 20:10:26


LTE_B25_CH26055_3M_16-QAM_1RB0



LTE_B25_CH26055_3M_16-QAM_15RB0




LTE_B25_CH26675_3M_QPSK_1RB14




Date: 16 DEC. 2019 19:51:42

LTE_B25_CH26675_3M_QPSK_15RB0




Date: 16 DEC. 2019 20:00:42

LTE_B25_CH26675_3M_16-QAM_1RB14




Date: 16.DEC.2019 19:52:07

LTE_B25_CH26675_3M_16-QAM_15RB0




Date: 16.DEC.2019 20:00:21

LTE_B25_CH26065_5M_QPSK_1RB0




Date: 16 DEC. 2019 20:20:36

LTE_B25_CH26065_5M_QPSK_25RB0




Date: 16 DEC. 2019 20:23:33

LTE_B25_CH26065_5M_16-QAM_1RB0




Date: 16 DEC.2019 20:20:55

LTE_B25_CH26065_5M_16-QAM_25RB0




Date: 16 DEC.2019 20:23:18

LTE_B25_CH26665_5M_QPSK_1RB24




Date: 16 DEC. 2019 20:27:59

LTE_B25_CH26665_5M_QPSK_25RB0




Date: 16 DEC. 2019 20:25:15

LTE_B25_CH26665_5M_16-QAM_1RB24




Date: 16 DEC. 2019 20:27:42

LTE_B25_CH26665_5M_16-QAM_25RB0




Date: 16 DEC. 2019 20:25:33

LTE_B25_CH26090_10M_QPSK_1RB0




Date: 16 DEC.2019 20:40:24

LTE_B25_CH26090_10M_QPSK_50RB0




Date: 16 DEC.2019 20:38:46

LTE_B25_CH26090_10M_16-QAM_1RB0




Date: 16.DEC.2019 20:40:04

LTE_B25_CH26090_10M_16-QAM_50RB0




Date: 16.DEC.2019 20:39:17

LTE_B25_CH26640_10M_QPSK_1RB49




Date: 16 DEC. 2019 20:33:46

LTE_B25_CH26640_10M_QPSK_50RB0




Date: 16 DEC. 2019 20:36:17

LTE_B25_CH26640_10M_16-QAM_1RB49




Date: 16.DEC.2019 20:34:50

LTE_B25_CH26640_10M_16-QAM_50RB0




Date: 16.DEC.2019 20:35:24

LTE_B25_CH26115_15M_QPSK_1RB0




Date: 16.DEC.2019 20:47:34

LTE_B25_CH26115_15M_QPSK_75RB0




Date: 16.DEC.2019 20:48:51


LTE_B25_CH26115_15M_16-QAM_1RB0



LTE_B25_CH26115_15M_16-QAM_75RB0




LTE_B25_CH26615_15M_QPSK_1RB74




Date: 16 DEC. 2019 20:56:53

LTE_B25_CH26615_15M_QPSK_75RB0




Date: 16 DEC. 2019 20:51:50

LTE_B25_CH26615_15M_16-QAM_1RB74




Date: 16 DEC. 2019 20:55:58

LTE_B25_CH26615_15M_16-QAM_75RB0




Date: 16 DEC. 2019 20:52:08

LTE_B25_CH26140_20M_QPSK_1RB0




Date: 17.DEC.2019 10:06:23

LTE_B25_CH26140_20M_QPSK_100RB0




Date: 17.DEC.2019 10:15:31


LTE_B25_CH26140_20M_16-QAM_1RB0



LTE_B25_CH26140_20M_16-QAM_100RB0




LTE_B25_CH26590_20M_QPSK_1RB99




Date: 17.DEC.2019 11:01:06

LTE_B25_CH26590_20M_QPSK_100RB0




Date: 17.DEC.2019 10:26:21

LTE_B25_CH26590_20M_16-QAM_1RB99



Date: 17.DEC.2019 10:44:02


LTE_B25_CH26590_20M_16-QAM_100RB0



Date: 17.DEC.2019 10:27:04


Product	Module		
Test Item	Spurious Emissions at Antenna Terminals (Part 22)		
Test Mode	Mode 7: LTE Band 26		
Date of Test	2019/12/14	Test Site	SR12-H
Temperature (°C)	22.0°C	Humidity (%RH)	54%RH

LTE_B26_CH26797_1.4M_QPSK_1RB0 (Part 22)




Date: 14 DEC.2019 15:05:47

LTE_B26_CH26797_1.4M_QPSK_6RB0 (Part 22)




Date: 14 DEC.2019 15:07:02

LTE_B26_CH26797_1.4M_16-QAM_1RB0 (Part 22)




Date: 14.DEC.2019 15:06:26

LTE_B26_CH26797_1.4M_16-QAM_6RB0 (Part 22)




Date: 14.DEC.2019 15:06:47

LTE_B26_CH27033_1.4M_QPSK_1RB5 (Part 22)




Date: 14, DEC, 2019 15:11:28

LTE_B26_CH27033_1.4M_QPSK_6RB0 (Part 22)




Date: 14, DEC, 2019 15:07:35

LTE_B26_CH27033_1.4M_16-QAM_1RB5 (Part 22)




Date: 14.DEC.2019 15:11:09

LTE_B26_CH27033_1.4M_16-QAM_6RB0 (Part 22)




Date: 14.DEC.2019 15:07:54

LTE_B26_CH26805_3M_QPSK_1RB0 (Part 22)




Date: 14, DEC, 2019 15:15:00

LTE_B26_CH26805_3M_QPSK_15RB0 (Part 22)




Date: 14, DEC, 2019 15:14:02

LTE_B26_CH27025_3M_QPSK_1RB14 (Part 22)




Date: 14, DEC, 2019 15:12:13

LTE_B26_CH27025_3M_QPSK_15RB0 (Part 22)




Date: 14, DEC, 2019 15:13:25

LTE_B26_CH27025_3M_16-QAM_1RB14 (Part 22)




Date: 14.DEC.2019 15:12:35

LTE_B26_CH27025_3M_16-QAM_15RB0 (Part 22)




Date: 14.DEC.2019 15:13:10

LTE_B26_CH26815_5M_QPSK_1RB0 (Part 22)




Date: 14, DEC, 2019 15:22:18

LTE_B26_CH26815_5M_QPSK_25RB0 (Part 22)




Date: 14, DEC, 2019 15:23:20

LTE_B26_CH26815_5M_16-QAM_1RB0 (Part 22)




Date: 14.DEC.2019 15:22:42

TE_B26_CH26815_5M_16-QAM_25RB0 (Part 22)




Date: 14.DEC.2019 15:23:07

LTE_B26_CH27015_5M_QPSK_1RB24 (Part 22)




Date: 14, DEC, 2019 15:25:38

LTE_B26_CH27015_5M_QPSK_25RB0 (Part 22)




Date: 14, DEC, 2019 15:24:44

LTE_B26_CH27015_5M_16-QAM_1RB24 (Part 22)




Date: 14, DEC, 2019 15:25:18

LTE_B26_CH27015_5M_16-QAM_25RB0 (Part 22)




Date: 14, DEC, 2019 15:24:58

LTE_B26_CH26840_10M_QPSK_1RB0 (Part 22)




Date: 14, DEC, 2019 15:47:28

LTE_B26_CH26840_10M_QPSK_50RB0 (Part 22)




Date: 14, DEC, 2019 15:39:25

LTE_B26_CH26840_10M_16-QAM_1RB0 (Part 22)




Date: 14, DEC, 2019 15:47:13

LTE_B26_CH26840_10M_16-QAM_50RB0 (Part 22)




Date: 14, DEC, 2019 15:39:48

LTE_B26_CH26990_10M_QPSK_1RB49 (Part 22)




Date: 14, DEC, 2019 15:29:09

LTE_B26_CH26990_10M_QPSK_50RB0 (Part 22)




Date: 14, DEC, 2019 15:30:43

LTE_B26_CH26990_10M_16-QAM_1RB49 (Part 22)




Date: 14, DEC, 2019 15:29:49

LTE_B26_CH26990_10M_16-QAM_50RB0 (Part 22)




Date: 14, DEC, 2019 15:30:26

LTE_B26_CH26865_15M_QPSK_1RB0 (Part 22)




Date: 14, DEC, 2019 15:50:28

LTE_B26_CH26865_15M_QPSK_75RB0 (Part 22)




Date: 14, DEC, 2019 15:51:59

LTE_B26_CH26865_15M_16-QAM_1RB0 (Part 22)




Date: 14.DEC.2019 15:50:54

LTE_B26_CH26865_15M_16-QAM_75RB0 (Part 22)




Date: 14.DEC.2019 15:51:45

LTE_B26_CH26965_15M_QPSK_1RB74 (Part 22)



Date: 14, DEC, 2019 15:53:46


LTE_B26_CH26965_15M_QPSK_75RB0 (Part 22)



Date: 14, DEC, 2019 15:52:53


Product	Module		
Test Item	Spurious Emissions at Antenna Terminals (Part 90)		
Test Mode	Mode 7: LTE Band 26		
Date of Test	2019/12/17	Test Site	SR12-H
Temperature (°C)	23.0°C	Humidity (%RH)	59%RH

LTE_B26_CH26697_1.4M_QPSK_1RB0 (Part 90)




Date: 17 DEC 2019 11:20:09

LTE_B26_CH26697_1.4M_QPSK_6RB0 (Part 90)




Date: 17 DEC 2019 11:26:25


LTE_B26_CH26697_1.4M_16-QAM_1RB0 (Part 90)



LTE_B26_CH26697_1.4M_16-QAM_6RB0 (Part 90)




LTE_B26_CH26783_1.4M_QPSK_1RB5 (Part 90)




Date: 17.DEC.2019 13:14:12

LTE_B26_CH26783_1.4M_QPSK_6RB0 (Part 90)




Date: 17.DEC.2019 13:12:59

LTE_B26_CH26783_1.4M_16-QAM_1RB5 (Part 90)




Date: 17.DEC.2019 13:13:54

LTE_B26_CH26783_1.4M_16-QAM_6RB0 (Part 90)




Date: 17.DEC.2019 13:13:19

LTE_B26_CH26705_3M_QPSK_1RB14 (Part 90)




Date: 17.DEC.2019 14:07:41

LTE_B26_CH26705_3M_QPSK_15RB0 (Part 90)




Date: 17.DEC.2019 13:59:59

LTE_B26_CH26705_3M_16-QAM_1RB14 (Part 90)




Date: 17.DEC.2019 14:05:55

LTE_B26_CH26705_3M_16-QAM_15RB0 (Part 90)




Date: 17.DEC.2019 14:00:22

LTE_B26_CH26775_3M_QPSK_1RB14 (Part 90)




Date: 17.DEC.2019 13:23:10

LTE_B26_CH26775_3M_QPSK_15RB0 (Part 90)




Date: 17.DEC.2019 13:50:48

LTE_B26_CH26775_3M_16-QAM_1RB14 (Part 90)




Date: 17.DEC.2019 13:23:45

LTE_B26_CH26775_3M_16-QAM_15RB0 (Part 90)




Date: 17.DEC.2019 13:43:15

LTE_B26_CH26715_5M_QPSK_1RB0 (Part 90)




Date: 17.DEC.2019 14:11:51

LTE_B26_CH26715_5M_QPSK_25RB0 (Part 90)




Date: 17.DEC.2019 14:29:51

LTE_B26_CH26715_5M_16-QAM_1RB0 (Part 90)




Date: 17.DEC.2019 14:22:27

LTE_B26_CH26715_5M_16-QAM_25RB0 (Part 90)




Date: 17.DEC.2019 14:25:22

LTE_B26_CH26765_5M_QPSK_1RB24 (Part 90)




Date: 17.DEC.2019 15:29:32

LTE_B26_CH26765_5M_QPSK_25RB0 (Part 90)




Date: 17.DEC.2019 14:58:55

LTE_B26_CH26765_5M_16-QAM_1RB24 (Part 90)




Date: 17.DEC.2019 15:23:02

LTE_B26_CH26765_5M_16-QAM_25RB0 (Part 90)




Date: 17.DEC.2019 14:59:56

LTE_B26_CH26740_10M_QPSK_1RB0 (Part 90)




Date: 17.DEC.2019 16:10:37

LTE_B26_CH26740_10M_QPSK_1RB49 (Part 90)




Date: 17.DEC.2019 15:40:34

LTE_B26_CH26740_10M_QPSK_50RB0 (Part 90)




LTE_B26_CH26740_10M_16-QAM_1RB0 (Part 90)




Date: 17.DEC.2019 16:08:48

LTE_B26_CH26740_10M_16-QAM_1RB49 (Part 90)



Date: 17.DEC.2019 15:41:37

LTE_B26_CH26740_10M_16-QAM_50RB0 (Part 90)



Date: 17.DEC.2019 16:12:55