



Band38-10MHz-16QAM-38200-1RB#0-Range4:1000~5000MHz




Date: 23.JUL.2019 11:31:17

Band38-10MHz-16QAM-38200-1RB#0-Range5:5000~12000MHz




Date: 23.JUL.2019 11:31:39

Band38-10MHz-16QAM-38200-1RB#0-Range6:12000~26500MHz




Date: 23.JUL.2019 13:24:47

Band38-15MHz-QPSK-37825-1RB#0-Range3:30~1000MHz




Date: 23.JUL.2019 11:34:00

Band38-15MHz-QPSK-37825-1RB#0-Range4:1000~5000MHz




Date: 23.JUL.2019 11:34:23

Band38-15MHz-QPSK-37825-1RB#0-Range5:5000~12000MHz




Date: 23.JUL.2019 11:34:46

Band38-15MHz-QPSK-37825-1RB#0-Range6:12000~26500MHz




Date: 23.JUL.2019 13:28:17

Band38-15MHz-QPSK-38000-1RB#0-Range3:30~1000MHz




Date: 23.JUL.2019 11:37:54

Band38-15MHz-QPSK-38000-1RB#0-Range4:1000~5000MHz




Date: 23.JUL.2019 11:38:17

Band38-15MHz-QPSK-38000-1RB#0-Range5:5000~12000MHz




Date: 23.JUL.2019 11:38:40

Band38-15MHz-QPSK-38000-1RB#0-Range6:12000~26500MHz




Date: 23.JUL.2019 13:32:11

Band38-15MHz-QPSK-38175-1RB#0-Range3:30~1000MHz




Date: 23.JUL.2019 11:41:49

Band38-15MHz-QPSK-38175-1RB#0-Range4:1000~5000MHz




Date: 23.JUL.2019 11:42:13

Band38-15MHz-QPSK-38175-1RB#0-Range5:5000~12000MHz




Date: 23.JUL.2019 11:42:35

Band38-15MHz-QPSK-38175-1RB#0-Range6:12000~26500MHz




Date: 23.JUL.2019 13:36:07

Band38-15MHz-16QAM-37825-1RB#0-Range3:30~1000MHz




Date: 23.JUL.2019 11:35:56

Band38-15MHz-16QAM-37825-1RB#0-Range4:1000~5000MHz




Date: 23.JUL.2019 11:36:19

Band38-15MHz-16QAM-37825-1RB#0-Range5:5000~12000MHz




Date: 23.JUL.2019 11:36:42

Band38-15MHz-16QAM-37825-1RB#0-Range6:12000~26500MHz




Date: 23.JUL.2019 13:30:13

Band38-15MHz-16QAM-38000-1RB#0-Range3:30~1000MHz




Date: 23.JUL.2019 11:39:49

Band38-15MHz-16QAM-38000-1RB#0-Range4:1000~5000MHz




Date: 23.JUL.2019 11:40:13

Band38-15MHz-16QAM-38000-1RB#0-Range5:5000~12000MHz




Date: 23.JUL.2019 11:40:36

Band38-15MHz-16QAM-38000-1RB#0-Range6:12000~26500MHz




Date: 23.JUL.2019 13:34:07

Band38-15MHz-16QAM-38175-1RB#0-Range3:30~1000MHz




Date: 23.JUL.2019 11:43:45

Band38-15MHz-16QAM-38175-1RB#0-Range4:1000~5000MHz




Date: 23.JUL.2019 11:44:09

Band38-15MHz-16QAM-38175-1RB#0-Range5:5000~12000MHz




Date: 23.JUL.2019 11:44:31

Band38-15MHz-16QAM-38175-1RB#0-Range6:12000~26500MHz




Date: 23.JUL.2019 13:38:03

Band38-20MHz-QPSK-37850-1RB#0-Range2:0.15~30MHz




Date: 23.JUL.2019 11:47:05

Band38-20MHz-QPSK-37850-1RB#0-Range3:30~1000MHz




Date: 23.JUL.2019 11:47:16

Band38-20MHz-QPSK-37850-1RB#0-Range4:1000~5000MHz




Date: 23.JUL.2019 11:47:40

Band38-20MHz-QPSK-37850-1RB#0-Range5:5000~12000MHz




Date: 23.JUL.2019 11:48:02

Band38-20MHz-QPSK-37850-1RB#0-Range6:12000~26500MHz




Date: 23.JUL.2019 13:41:20

Band38-20MHz-QPSK-38000-1RB#0-Range3:30~1000MHz




Date: 23.JUL.2019 11:51:11

Band38-20MHz-QPSK-38000-1RB#0-Range4:1000~5000MHz




Date: 23.JUL.2019 11:51:34

Band38-20MHz-QPSK-38000-1RB#0-Range5:5000~12000MHz




Date: 23.JUL.2019 11:51:57

Band38-20MHz-QPSK-38000-1RB#0-Range6:12000~26500MHz




Date: 23.JUL.2019 13:45:15

Band38-20MHz-QPSK-38150-1RB#0-Range3:30~1000MHz




Date: 23.JUL.2019 11:55:07

Band38-20MHz-QPSK-38150-1RB#0-Range4:1000~5000MHz




Date: 23.JUL.2019 11:55:31

Band38-20MHz-QPSK-38150-1RB#0-Range5:5000~12000MHz




Date: 23.JUL.2019 11:55:53

Band38-20MHz-QPSK-38150-1RB#0-Range6:12000~26500MHz




Date: 23.JUL.2019 13:49:11

Band38-20MHz-16QAM-37850-1RB#0-Range3:30~1000MHz




Date: 23.JUL.2019 11:49:12

Band38-20MHz-16QAM-37850-1RB#0-Range4:1000~5000MHz




Date: 23.JUL.2019 11:49:36

Band38-20MHz-16QAM-37850-1RB#0-Range5:5000~12000MHz




Date: 23.JUL.2019 11:49:58

Band38-20MHz-16QAM-37850-1RB#0-Range6:12000~26500MHz




Date: 23.JUL.2019 13:43:16

Band38-20MHz-16QAM-38000-1RB#0-Range3:30~1000MHz




Date: 23.JUL.2019 11:53:07

Band38-20MHz-16QAM-38000-1RB#0-Range4:1000~5000MHz




Date: 23.JUL.2019 11:53:31

Band38-20MHz-16QAM-38000-1RB#0-Range5:5000~12000MHz




Date: 23.JUL.2019 11:53:53

Band38-20MHz-16QAM-38000-1RB#0-Range6:12000~26500MHz




Date: 23.JUL.2019 13:47:11

Band38-20MHz-16QAM-38150-1RB#0-Range3:30~1000MHz




Date: 23.JUL.2019 11:57:03

Band38-20MHz-16QAM-38150-1RB#0-Range4:1000~5000MHz




Date: 23.JUL.2019 11:57:27

Band38-20MHz-16QAM-38150-1RB#0-Range5:5000~12000MHz



Date: 23.JUL.2019 11:57:50


Band38-20MHz-16QAM-38150-1RB#0-Range6:12000~26500MHz



Date: 23.JUL.2019 13:51:07


LTE Band 41:

Band41_5MHz_QPSK_40265_1RB#0




Date: 3.JUL.2019 14:13:09

Band41_5MHz_QPSK_40265_1RB#0




Date: 3.JUL.2019 14:13:33

Band41_5MHz_QPSK_40265_1RB#0




Date: 3.JUL.2019 14:13:55

Band41_5MHz_QPSK_40265_1RB#0




Date: 3.JUL.2019 14:14:18

Band41_5MHz_QPSK_40740_1RB#0




Date: 3.JUL.2019 14:16:42

Band41_5MHz_QPSK_40740_1RB#0




Date: 3.JUL.2019 14:17:06

Band41_5MHz_QPSK_40740_1RB#0




Date: 3.JUL.2019 14:17:29

Band41_5MHz_QPSK_40740_1RB#0




Date: 3.JUL.2019 14:17:52

Band41_5MHz_QPSK_41215_1RB#0




Date: 3.JUL.2019 14:21:20

Band41_5MHz_QPSK_41215_1RB#0




Date: 3.JUL.2019 14:21:45

Band41_5MHz_QPSK_41215_1RB#0




Date: 3.JUL.2019 14:22:07

Band41_5MHz_QPSK_41215_1RB#0




Date: 3.JUL.2019 14:22:30

Band41_5MHz_16QAM_40265_1RB#0




Date: 3.JUL.2019 14:14:54

Band41_5MHz_16QAM_40265_1RB#0




Date: 3.JUL.2019 14:15:18

Band41_5MHz_16QAM_40265_1RB#0




Date: 3.JUL.2019 14:15:41

Band41_5MHz_16QAM_40265_1RB#0




Date: 3.JUL.2019 14:16:04

Band41_5MHz_16QAM_40740_1RB#0




Date: 3.JUL.2019 14:18:28

Band41_5MHz_16QAM_40740_1RB#0




Date: 3.JUL.2019 14:18:52

Band41_5MHz_16QAM_40740_1RB#0




Date: 3.JUL.2019 14:19:15

Band41_5MHz_16QAM_40740_1RB#0




Date: 3.JUL.2019 14:19:38

Band41_5MHz_16QAM_41215_1RB#0




Date: 3.JUL.2019 14:23:06

Band41_5MHz_16QAM_41215_1RB#0




Date: 3.JUL.2019 14:23:30

Band41_5MHz_16QAM_41215_1RB#0




Date: 3.JUL.2019 14:23:53

Band41_5MHz_16QAM_41215_1RB#0




Date: 3.JUL.2019 14:24:16

Band41_10MHz_QPSK_40290_1RB#0




Date: 3.JUL.2019 14:35:13

Band41_10MHz_QPSK_40290_1RB#0




Date: 3.JUL.2019 14:35:38

Band41_10MHz_QPSK_40290_1RB#0




Date: 3.JUL.2019 14:36:00

Band41_10MHz_QPSK_40290_1RB#0




Date: 3.JUL.2019 14:36:23

Band41_10MHz_QPSK_40740_1RB#0




Date: 3.JUL.2019 14:38:47

Band41_10MHz_QPSK_40740_1RB#0




Date: 3.JUL.2019 14:39:11

Band41_10MHz_QPSK_40740_1RB#0




Date: 3.JUL.2019 14:39:34

Band41_10MHz_QPSK_40740_1RB#0




Date: 3.JUL.2019 14:39:57

Band41_10MHz_QPSK_41190_1RB#0




Date: 3.JUL.2019 14:43:25

Band41_10MHz_QPSK_41190_1RB#0




Date: 3.JUL.2019 14:43:49

Band41_10MHz_QPSK_41190_1RB#0




Date: 3.JUL.2019 14:44:12

Band41_10MHz_QPSK_41190_1RB#0




Date: 3.JUL.2019 14:44:35

Band41_10MHz_16QAM_40290_1RB#0




Date: 3.JUL.2019 14:36:59

Band41_10MHz_16QAM_40290_1RB#0




Date: 3.JUL.2019 14:37:23

Band41_10MHz_16QAM_40290_1RB#0




Date: 3.JUL.2019 14:37:46

Band41_10MHz_16QAM_40290_1RB#0




Date: 3.JUL.2019 14:38:09

Band41_10MHz_16QAM_40740_1RB#0




Date: 3.JUL.2019 14:48:33

Band41_10MHz_16QAM_40740_1RB#0




Date: 3.JUL.2019 14:48:57

Band41_10MHz_16QAM_40740_1RB#0




Date: 3.JUL.2019 14:41:20

Band41_10MHz_16QAM_40740_1RB#0




Date: 3.JUL.2019 14:41:42

Band41_10MHz_16QAM_41190_1RB#0




Date: 3.JUL.2019 14:45:11

Band41_10MHz_16QAM_41190_1RB#0




Date: 3.JUL.2019 14:45:35

Band41_10MHz_16QAM_41190_1RB#0




Date: 3.JUL.2019 14:45:58

Band41_10MHz_16QAM_41190_1RB#0




Date: 3.JUL.2019 14:46:20

Band41_15MHz_QPSK_40315_1RB#0




Date: 3.JUL.2019 14:54:35

Band41_15MHz_QPSK_40315_1RB#0




Date: 3.JUL.2019 14:54:59

Band41_15MHz_QPSK_40315_1RB#0




Date: 3.JUL.2019 14:55:22

Band41_15MHz_QPSK_40315_1RB#0




Date: 3.JUL.2019 14:55:44

Band41_15MHz_QPSK_40740_1RB#0




Date: 3.JUL.2019 14:58:09

Band41_15MHz_QPSK_40740_1RB#0




Date: 3.JUL.2019 14:58:33

Band41_15MHz_QPSK_40740_1RB#0




Date: 3.JUL.2019 14:58:56

Band41_15MHz_QPSK_40740_1RB#0




Date: 3.JUL.2019 14:59:18

Band41_15MHz_QPSK_41165_1RB#0




Date: 3.JUL.2019 15:02:47

Band41_15MHz_QPSK_41165_1RB#0




Date: 3.JUL.2019 15:03:11

Band41_15MHz_QPSK_41165_1RB#0




Date: 3.JUL.2019 15:03:34

Band41_15MHz_QPSK_41165_1RB#0




Date: 3.JUL.2019 15:03:57

Band41_15MHz_16QAM_40315_1RB#0




Date: 3.JUL.2019 14:56:20

Band41_15MHz_16QAM_40315_1RB#0




Date: 3.JUL.2019 14:56:45

Band41_15MHz_16QAM_40315_1RB#0




Date: 3.JUL.2019 14:57:07

Band41_15MHz_16QAM_40315_1RB#0




Date: 3.JUL.2019 14:57:30

Band41_15MHz_16QAM_40740_1RB#0




Date: 3.JUL.2019 14:59:54

Band41_15MHz_16QAM_40740_1RB#0




Date: 3.JUL.2019 15:00:18

Band41_15MHz_16QAM_40740_1RB#0




Date: 3.JUL.2019 15:00:41

Band41_15MHz_16QAM_40740_1RB#0




Date: 3.JUL.2019 15:01:04

Band41_15MHz_16QAM_41165_1RB#0




Date: 3.JUL.2019 15:04:33

Band41_15MHz_16QAM_41165_1RB#0




Date: 3.JUL.2019 15:04:57

Band41_15MHz_16QAM_41165_1RB#0




Date: 3.JUL.2019 15:05:19

Band41_15MHz_16QAM_41165_1RB#0




Date: 3.JUL.2019 15:05:42

Band41_20MHz_QPSK_40340_1RB#0




Date: 3.JUL.2019 15:15:21

Band41_20MHz_QPSK_40340_1RB#0




Date: 3.JUL.2019 15:15:45

Band41_20MHz_QPSK_40340_1RB#0




Date: 3.JUL.2019 15:16:07

Band41_20MHz_QPSK_40340_1RB#0




Date: 3.JUL.2019 15:16:30

Band41_20MHz_QPSK_40740_1RB#0




Date: 3.JUL.2019 15:18:54

Band41_20MHz_QPSK_40740_1RB#0




Date: 3.JUL.2019 15:19:18

Band41_20MHz_QPSK_40740_1RB#0




Date: 3.JUL.2019 15:19:41

Band41_20MHz_QPSK_40740_1RB#0




Date: 3.JUL.2019 15:20:03

Band41_20MHz_QPSK_41140_1RB#0




Date: 3.JUL.2019 15:23:33

Band41_20MHz_QPSK_41140_1RB#0




Date: 3.JUL.2019 15:23:57

Band41_20MHz_QPSK_41140_1RB#0




Date: 3.JUL.2019 15:24:20

Band41_20MHz_QPSK_41140_1RB#0




Date: 3.JUL.2019 15:24:42

Band41_20MHz_16QAM_40340_1RB#0




Date: 3.JUL.2019 15:17:06

Band41_20MHz_16QAM_40340_1RB#0




Date: 3.JUL.2019 15:17:30

Band41_20MHz_16QAM_40340_1RB#0




Date: 3.JUL.2019 15:17:53

Band41_20MHz_16QAM_40340_1RB#0




Date: 3.JUL.2019 15:18:15

Band41_20MHz_16QAM_40740_1RB#0




Date: 3.JUL.2019 15:20:40

Band41_20MHz_16QAM_40740_1RB#0




Date: 3.JUL.2019 15:21:04

Band41_20MHz_16QAM_40740_1RB#0




Date: 3.JUL.2019 15:21:27

Band41_20MHz_16QAM_40740_1RB#0




Date: 3.JUL.2019 15:21:49

Band41_20MHz_16QAM_41140_1RB#0




Date: 3.JUL.2019 15:25:19

Band41_20MHz_16QAM_41140_1RB#0




Date: 3.JUL.2019 15:25:43

Band41_20MHz_16QAM_41140_1RB#0





Date: 3.JUL.2019 15:26:06

Band41_20MHz_16QAM_41140_1RB#0





Date: 3.JUL.2019 15:26:28


Band edge measurement
Test Band = GSM850
Test Mode = GSM /TM1
Test Channel = LCH/HCH




Band edge measurement
 Test Band = GSM850
 Test Mode = EDGE /TM2
 Test Channel = LCH/HCH



Band edge measurement
 Test Band = GSM1900
 Test Mode = GSM /TM1
 Test Channel = LCH/HCH




Date: 2.JUL.2019 16:43:15




Date: 2.JUL.2019 16:44:10

Band edge measurement
 Test Band = GSM1900
 Test Mode = EDGE /TM1
 Test Channel = LCH/HCH





Date: 2.JUL.2019 17:15:58




Date: 2.JUL.2019 17:16:48


Band edge measurement
 Test Band = WCDMA850
 Test Mode = UMTS /TM3
 Test Channel = LCH/HCH



Band edge measurement
 Test Band = WCDMA1900
 Test Mode = UMTS /TM3
 Test Channel = LCH/HCH




Date: 2.JUL.2019 15:41:49



Date: 2.JUL.2019 15:42:18


LTE Band 2:

Band2_1.4MHz_QPSK_18607_1RB#0




Date: 25.JUN.2019 18:33:15

Band2_1.4MHz_QPSK_18607_6RB#0




Date: 3.JUL.2019 16:02:44

Band2_1.4MHz_QPSK_19193_1RB#5




Date: 25.JUN.2019 18:34:49

Band2_1.4MHz_QPSK_19193_6RB#0




Date: 3.JUL.2019 16:03:55

Band2_1.4MHz_16QAM_18607_1RB#0




Date: 25.JUN.2019 18:33:25

Band2_1.4MHz_16QAM_18607_6RB#0




Date: 3.JUL.2019 16:02:54

Band2_1.4MHz_16QAM_19193_1RB#5




Date: 25.JUN.2019 18:34:59

Band2_1.4MHz_16QAM_19193_6RB#0




Date: 3.JUL.2019 16:04:05

Band2_3MHz_QPSK_18615_1RB#0




Date: 25.JUN.2019 18:36:54

Band2_3MHz_QPSK_18615_15RB#0




Date: 3.JUL.2019 16:19:38

Band2_3MHz_QPSK_19185_1RB#14




Date: 25.JUN.2019 18:38:27

Band2_3MHz_QPSK_19185_15RB#0




Date: 3.JUL.2019 16:28:49

Band2_3MHz_16QAM_18615_1RB#0




Date: 25.JUN.2019 18:37:04

Band2_3MHz_16QAM_18615_15RB#0




Date: 3.JUL.2019 16:19:47

Band2_3MHz_16QAM_19185_1RB#14




Date: 25.JUN.2019 18:38:37

Band2_3MHz_16QAM_19185_15RB#0




Date: 3.JUL.2019 16:28:58

Band2_5MHz_QPSK_18625_1RB#0




Date: 11.JUL.2019 13:01:54

Band2_5MHz_QPSK_18625_25RB#0




Date: 11.JUL.2019 13:02:34

Band2_5MHz_QPSK_19175_1RB#24




Date: 11.JUL.2019 13:03:17

Band2_5MHz_QPSK_19175_25RB#0




Date: 11.JUL.2019 13:03:36

Band2_5MHz_16QAM_18625_1RB#0




Date: 11.JUL.2019 13:02:05

Band2_5MHz_16QAM_18625_25RB#0




Date: 11.JUL.2019 13:02:44

Band2_5MHz_16QAM_19175_1RB#24




Date: 11.JUL.2019 13:03:27

Band2_5MHz_16QAM_19175_25RB#0




Date: 11.JUL.2019 13:03:46

Band2_10MHz_QPSK_18650_1RB#0




Date: 25.JUN.2019 18:44:10

Band2_10MHz_QPSK_18650_50RB#0




Date: 3.JUL.2019 17:06:12

Band2_10MHz_QPSK_19150_1RB#49




Date: 25.JUN.2019 18:45:45

Band2_10MHz_QPSK_19150_50RB#0




Date: 3.JUL.2019 17:07:24

Band2_10MHz_16QAM_18650_1RB#0




Date: 25.JUN.2019 18:44:21

Band2_10MHz_16QAM_18650_50RB#0




Date: 3.JUL.2019 17:06:22

Band2_10MHz_16QAM_19150_1RB#49




Date: 25.JUN.2019 18:45:55

Band2_10MHz_16QAM_19150_50RB#0




Date: 3.JUL.2019 17:07:34

Band2_15MHz_QPSK_18675_1RB#0




Date: 25.JUN.2019 18:47:51

Band2_15MHz_QPSK_18675_75RB#0




Date: 3.JUL.2019 17:21:00

Band2_15MHz_QPSK_19125_1RB#74




Date: 25.JUN.2019 18:49:29

Band2_15MHz_QPSK_19125_75RB#0




Date: 3.JUL.2019 17:22:14

Band2_15MHz_16QAM_18675_1RB#0




Date: 25.JUN.2019 18:48:02

Band2_15MHz_16QAM_18675_75RB#0




Date: 3.JUL.2019 17:21:11

Band2_15MHz_16QAM_19125_1RB#74




Date: 25.JUN.2019 18:49:39

Band2_15MHz_16QAM_19125_75RB#0




Date: 3.JUL.2019 17:22:25

Band2_20MHz_QPSK_18700_1RB#0




Date: 25.JUN.2019 18:51:39

Band2_20MHz_QPSK_18700_100RB#0




Date: 3.JUL.2019 17:48:19

Band2_20MHz_QPSK_19100_1RB#99




Date: 25.JUN.2019 18:53:27

Band2_20MHz_QPSK_19100_100RB#0




Date: 3.JUL.2019 17:41:28

Band2_20MHz_16QAM_18700_1RB#0




Date: 25.JUN.2019 18:51:51

Band2_20MHz_16QAM_18700_100RB#0




Date: 3.JUL.2019 17:48:21

Band2_20MHz_16QAM_19100_1RB#99




Date: 25.JUN.2019 18:53:38

Band2_20MHz_16QAM_19100_100RB#0




Date: 3.JUL.2019 17:41:40

LTE Band 4:




Band4_1.4MHz_QPSK_20393_1RB#5




Date: 26.JUN.2019 12:49:53

Band4_1.4MHz_QPSK_20393_6RB#0




Date: 3.JUL.2019 17:46:12

Band4_1.4MHz_16QAM_19957_1RB#0




Date: 26.JUN.2019 12:47:45

Band4_1.4MHz_16QAM_19957_6RB#0




Date: 3.JUL.2019 17:45:11

Band4_1.4MHz_16QAM_20393_1RB#5




Date: 26.JUN.2019 12:50:03

Band4_1.4MHz_16QAM_20393_6RB#0




Date: 3.JUL.2019 17:46:22

Band4_3MHz_QPSK_19965_1RB#0




Date: 26.JUN.2019 12:51:10

Band4_3MHz_QPSK_19965_15RB#0




Date: 3.JUL.2019 18:00:43

Band4_3MHz_QPSK_20385_1RB#14




Date: 26.JUN.2019 12:52:43

Band4_3MHz_QPSK_20385_15RB#0




Date: 3.JUL.2019 18:01:53

Band4_3MHz_16QAM_19965_1RB#0




Date: 26.JUN.2019 12:51:20

Band4_3MHz_16QAM_19965_15RB#0




Date: 3.JUL.2019 18:00:52

Band4_3MHz_16QAM_20385_1RB#14




Date: 26.JUN.2019 12:52:53

Band4_3MHz_16QAM_20385_15RB#0




Date: 3.JUL.2019 18:02:03

Band4_5MHz_QPSK_19975_1RB#0




Date: 11.JUL.2019 13:45:20

Band4_5MHz_QPSK_19975_25RB#0




Date: 11.JUL.2019 13:45:58

Band4_5MHz_QPSK_20375_1RB#24




Date: 11.JUL.2019 13:46:41

Band4_5MHz_QPSK_20375_25RB#0




Date: 11.JUL.2019 13:47:00

Band4_5MHz_16QAM_19975_1RB#0




Date: 11.JUL.2019 13:45:29

Band4_5MHz_16QAM_19975_25RB#0




Date: 11.JUL.2019 13:46:08

Band4_5MHz_16QAM_20375_1RB#24




Date: 11.JUL.2019 13:46:50

Band4_5MHz_16QAM_20375_25RB#0




Date: 11.JUL.2019 13:47:10

Band4_10MHz_QPSK_20000_1RB#0




Date: 26.JUN.2019 13:02:42

Band4_10MHz_QPSK_20000_50RB#0




Date: 3.JUL.2019 18:34:56

Band4_10MHz_QPSK_20350_1RB#49




Date: 26.JUN.2019 13:04:15

Band4_10MHz_QPSK_20350_50RB#0




Date: 3.JUL.2019 18:36:07

Band4_10MHz_16QAM_20000_1RB#0




Date: 26.JUN.2019 13:02:52

Band4_10MHz_16QAM_20000_50RB#0




Date: 3.JUL.2019 18:35:06

Band4_10MHz_16QAM_20350_1RB#49




Date: 26.JUN.2019 13:04:25

Band4_10MHz_16QAM_20350_50RB#0




Date: 3.JUL.2019 18:36:17

Band4_15MHz_QPSK_20025_1RB#0




Date: 26.JUN.2019 13:06:23

Band4_15MHz_QPSK_20025_75RB#0




Date: 3.JUL.2019 18:51:44

Band4_15MHz_QPSK_20325_1RB#74




Date: 26.JUN.2019 13:07:59

Band4_15MHz_QPSK_20325_75RB#0




Date: 3.JUL.2019 18:52:58

Band4_15MHz_16QAM_20025_1RB#0




Date: 26.JUN.2019 13:06:33

Band4_15MHz_16QAM_20025_75RB#0




Date: 3.JUL.2019 18:51:55

Band4_15MHz_16QAM_20325_1RB#74




Date: 26.JUN.2019 13:00:10

Band4_15MHz_16QAM_20325_75RB#0




Date: 3.JUL.2019 18:53:08

Band4_20MHz_QPSK_20050_1RB#0




Date: 26.JUN.2019 13:10:09

Band4_20MHz_QPSK_20050_100RB#0




Date: 3.JUL.2019 19:21:56

Band4_20MHz_QPSK_20300_1RB#99




Date: 26.JUN.2019 13:11:56

Band4_20MHz_QPSK_20300_100RB#0




Date: 3.JUL.2019 19:23:14

Band4_20MHz_16QAM_20050_1RB#0




Date: 26.JUN.2019 13:10:21

Band4_20MHz_16QAM_20050_100RB#0




Date: 3.JUL.2019 19:22:07

Band4_20MHz_16QAM_20300_1RB#99



Date: 26.JUN.2019 13:12:08


Band4_20MHz_16QAM_20300_100RB#0




Date: 3.JUL.2019 19:23:25

LTE Band 5:


Band5 1.4MHz QPSK 20407 1RB#0



Band5 1.4MHz QPSK 20407 6RB#0




Band5 1.4MHz_QPSK 20643 1RB#5




Band5 1.4MHz_QPSK 20643 6RB#0




Band5 1.4MHz 16QAM 20407 1RB#0



Band5 1.4MHz 16QAM 20407 6RB#0



Band5 1.4MHz 16QAM 20643 1RB#5



Band5 1.4MHz 16QAM 20643 6RB#0



Band5_3MHz_QPSK_20415_1RB#0



Band5_3MHz_QPSK_20415_15RB#0



Band5_3MHz_QPSK_20635_1RB#14



Band5_3MHz_QPSK_20635_15RB#0



Band5_3MHz_16QAM_20415_1RB#0



Band5_3MHz_16QAM_20415_15RB#0



Band5 3MHz 16QAM 20635 1RB#14



Band5 3MHz 16QAM 20635 15RB#0



Band5 5MHz QPSK 20425 1RB#0



Band5 5MHz QPSK 20425 25RB#0



Band5_5MHz_QPSK_20625_1RB#24



Band5_5MHz_QPSK_20625_25RB#0



Band5_5MHz_16QAM_20425_1RB#0



Band5_5MHz_16QAM_20425_25RB#0



Band5 5MHz 16QAM 20625 1RB#24



Band5 5MHz 16QAM 20625 25RB#0



Band5_10MHz_QPSK_20450_1RB#0



Band5_10MHz_QPSK_20450_50RB#0



Band5 10MHz QPSK 20600 1RB#49



Band5 10MHz QPSK 20600 50RB#0



Band5 10MHz 16QAM 20450 1RB#0



Band5 10MHz 16QAM 20450 50RB#0



Band5 10MHz 16QAM 20600 1RB#49




Band5 10MHz 16QAM 20600 50RB#0




LTE Band 7:

Band7_5MHz_QPSK_20775_1RB#0




Date: 26.JUN.2019 22:22:12

Band7_5MHz_QPSK_20775_25RB#0




Date: 3.JUL.2019 12:37:13

Band7_5MHz_QPSK_21425_1RB#24




Date: 3.JUL.2019 12:38:08

Band7_5MHz_QPSK_21425_25RB#0




Date: 3.JUL.2019 12:38:28

Band7_5MHz_16QAM_20775_1RB#0




Date: 26.JUN.2019 22:22:22

Band7_5MHz_16QAM_20775_25RB#0




Date: 3.JUL.2019 12:37:23

Band7_5MHz_16QAM_21425_1RB#24




Date: 3.JUL.2019 12:38:18

Band7_5MHz_16QAM_21425_25RB#0




Date: 3.JUL.2019 12:38:39

Band7_10MHz_QPSK_20800_1RB#0




Date: 3.JUL.2019 12:43:11

Band7_10MHz_QPSK_20800_50RB#0




Date: 3.JUL.2019 12:43:53

Band7_10MHz_QPSK_21400_1RB#49




Date: 3.JUL.2019 12:44:49

Band7_10MHz_QPSK_21400_50RB#0




Date: 3.JUL.2019 12:45:10

Band7_10MHz_16QAM_20800_1RB#0




Date: 3.JUL.2019 12:43:21

Band7_10MHz_16QAM_20800_50RB#0




Date: 3.JUL.2019 12:44:04

Band7 10MHz 16QAM 21400 1RB#49




Date: 3.JUL.2019 12:44:59

Band7 10MHz 16QAM 21400 50RB#0




Date: 3.JUL.2019 12:45:21

Band7_15MHz_QPSK_20825_1RB#0




Date: 3.JUL.2019 13:12:20

Band7_15MHz_QPSK_20825_75RB#0




Date: 9.JUL.2019 17:15:56

Band7_15MHz_QPSK_21375_1RB#74



Date: 3.JUL.2019 13:14:01

Band7_15MHz_QPSK_21375_75RB#0



Date: 9.JUL.2019 17:17:16