


3. Internal Photograph of EUT

Brand Name: Motorola; Model Name: XT2345-2






Brand Name: Motorola; Model Name: XT2345-2




Brand Name: Motorola; Model Name: XT2345-2




Brand Name: Motorola; Model Name: XT2345-2




Brand Name: Motorola; Model Name: XT2345-2



Brand Name: Motorola; Model Name: XT2345-2



Brand Name: Motorola; Model Name: XT2345-2




Brand Name: Motorola; Model Name: XT2345-2






Brand Name: Motorola; Model Name: XT2345-2







Brand Name: Motorola; Model Name: XT2345-2



Brand Name: Motorola; Model Name: XT2345-2




Brand Name: Motorola; Model Name: XT2345-2






Brand Name: Motorola; Model Name: XT2345-2






Brand Name: Motorola; Model Name: XT2345-2



Brand Name: Motorola; Model Name: XT2345-2




Brand Name: Motorola; Model Name: XT2345-2







Brand Name: Motorola; Model Name: XT2345-2




Brand Name: Motorola; Model Name: XT2345-2




Brand Name: Motorola; Model Name: XT2345-2




Brand Name: Motorola; Model Name: XT2345-2




Brand Name: Motorola; Model Name: XT2345-2



Brand Name: Motorola; Model Name: XT2345-2




Brand Name: Motorola; Model Name: XT2345-2







Brand Name: Motorola; Model Name: XT2345-2




Brand Name: Motorola; Model Name: XT2345-2



Brand Name: Motorola; Model Name: XT2345-2




Brand Name: Motorola; Model Name: XT2345-2







Brand Name: Motorola; Model Name: XT2345-2




Brand Name: Motorola; Model Name: XT2345-2



Brand Name: Motorola; Model Name: XT2345-2



Brand Name: Motorola; Model Name: XT2345-2



Brand Name: Motorola; Model Name: XT2345-2

