

Scott McCutchan

To: kyle@celectronics.com
Subject: FCC ID: AAO1502117

Mr. Fujimoto:

In order for processing of this application (FCC ID: AAO1502117) to continue, the following issue(s) will have to be addressed:

1) The FCC label of the module that was submitted does not meet the requirements of section 15.17(a)(3). The following compliance statement must also be on the device label:

"This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation."

There are some cases, where having only the FCC ID on the product is acceptable, but only when the device is smaller than a man's palm. Judging by the photos submitted, this device does not meet that exemption.

2) The FCC ID on page 23 of the user's manual does not meet the requirements of section 2.925(a)(1). It should read: "FCC ID: AAO1502117". There should be no number sign (#) between the FCC ID and the colon. Please submit only this corrected page from the user's manual.

The item(s) indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 60 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted.

Correspondence to this e-mail must be uploaded onto our website, with a correspondence number of: AAO1502117-1.

Any questions about the content of this correspondence should be directed to scott@celectronics.com.

If you have any questions, feel free to contact me.

Best regards,

Scott McCutchan
Operations Manager
Compatible Electronics TCB
(714) 579-1489
fax (714) 579-1850
<http://www.celectronics.com>

Correspondence by Project

Project Number:

1027700173

Correspondence Number	Memo
AAO1502117-1	<p>1) The FCC label of the module that was submitted does not meet the requirements of section 15.17(a)(3). The following compliance statement must also be on the device label: Response: The label has been revised. Please see the revised FCC-ID Label in exhibits. 2) The FCC ID on page 23 of the user's manual does not meet the requirements of section 2.925(a)(1). It should read: "FCC ID: AAO1502117". There should be no number sign (#) between the FCC ID and the colon. Please submit only this corrected page from the user's manual. Response: This page has been revised. Please see the revised page 23 of the user's manual in exhibits.</p>