

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 18 Subpart C
APYDMR0182
23-0051
May 24, 2023
Sharp Corporation
SWB3085HS

Internal Photos:

The microwave drawer was separated from the convection oven for these photographs.




Figure 1. Magnetron in EUT

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 18 Subpart C
APYDMR0182
23-0051
May 24, 2023
Sharp Corporation
SWB3085HS



Figure 2. Close-up of Magnetron Label in situ

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 18 Subpart C
APYDMR0182
23-0051
May 24, 2023
Sharp Corporation
SWB3085HS




Figure 3. Rear View

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 18 Subpart C
APYDMR0182
23-0051
May 24, 2023
Sharp Corporation
SWB3085HS




Figure 4. Left Side

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 18 Subpart C
APYDMR0182
23-0051
May 24, 2023
Sharp Corporation
SWB3085HS




Figure 5. Right Side

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 18 Subpart C
APYDMR0182
23-0051
May 24, 2023
Sharp Corporation
SWB3085HS




Figure 6. Top Side

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 18 Subpart C
APYDMR0182
23-0051
May 24, 2023
Sharp Corporation
SWB3085HS




Figure 7. Rear Display Panel top of Convection Oven

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 18 Subpart C
APYDMR0182
23-0051
May 24, 2023
Sharp Corporation
SWB3085HS




Figure 8. Electrical section of the top of Convection Oven

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 18 Subpart C
APYDMR0182
23-0051
May 24, 2023
Sharp Corporation
SWB3085HS



Figure 9. Front of Display PCBA

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 18 Subpart C
APYDMR0182
23-0051
May 24, 2023
Sharp Corporation
SWB3085HS



Figure 10. Back of Display PCBA

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 18 Subpart C
APYDMR0182
23-0051
May 24, 2023
Sharp Corporation
SWB3085HS



Figure 11. Wi-Fi radio module and host interface board #1

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 18 Subpart C
APYDMR0182
23-0051
May 24, 2023
Sharp Corporation
SWB3085HS



Figure 12. Wi-Fi radio module and host interface board #2

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 18 Subpart C
APYDMR0182
23-0051
May 24, 2023
Sharp Corporation
SWB3085HS




Figure 13. Wi-Fi modules on host interface boards, Top View

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 18 Subpart C
APYDMR0182
23-0051
May 24, 2023
Sharp Corporation
SWB3085HS




Figure 14. Wi-Fi modules on host interface boards, Bottom View