



802.11n40_2422MHz_Chain 0 -28.56dBm/3kHz




ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 30.AUG.2024 11:55:49

802.11n40_2442MHz_Chain 0 -28.69dBm/3kHz




ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 30.AUG.2024 11:59:38

802.11n40_2462MHz_Chain 0 -28.17dBm/3kHz




ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 30.AUG.2024 13:24:33

802.11n40_2422MHz_Chain 1 -29.03dBm/3kHz




ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 30.AUG.2024 14:08:19

802.11n40_2442MHz_Chain 1 -29.26dBm/3kHz



ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 30.AUG.2024 14:12:29

802.11n40_2462MHz_Chain 1 -28.45dBm/3kHz




ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 30.AUG.2024 14:16:54

Conducted emission at Antenna Terminals


2412~2472

802.11b_2412MHz_Chain 0




ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 20.DEC.2024 11:38:33

802.11b_2442MHz_Chain 0




ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 20.DEC.2024 11:39:26

802.11b_2472MHz_Chain 0




ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 20.DEC.2024 11:41:43

802.11b_2412MHz_Chain 1




ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 20.DEC.2024 14:03:16

802.11b_2442MHz_Chain 1




ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 20.DEC.2024 14:04:03

802.11b_2472MHz_Chain 1




ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 20.DEC.2024 14:05:00

802.11g_2412MHz_Chain 0




ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 20.DEC.2024 11:43:19

802.11g_2442MHz_Chain 0




ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 20.DEC.2024 11:46:30

802.11g_2472MHz_Chain 0




ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 20.DEC.2024 11:47:49

802.11g_2412MHz_Chain 1




ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 20.DEC.2024 14:07:19

802.11g_2442MHz_Chain 1




ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 20.DEC.2024 14:08:15

802.11g_2472MHz_Chain 1




ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 20.DEC.2024 14:09:32

802.11n20_2412MHz_Chain 0




ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 20.DEC.2024 11:49:03

802.11n20_2442MHz_Chain 0




ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 20.DEC.2024 11:50:06

802.11n20_2472MHz_Chain 0




ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 20.DEC.2024 11:51:01

802.11n20_2412MHz_Chain 1




ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 20.DEC.2024 14:10:16

802.11n20_2442MHz_Chain 1




ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 20.DEC.2024 14:11:16

802.11n20_2472MHz_Chain 1




ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 20.DEC.2024 14:12:29

802.11n40_2422MHz_Chain 0




ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 20.DEC.2024 11:53:22

802.11n40_2442MHz_Chain 0




ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 20.DEC.2024 11:54:34

802.11n40_2462MHz_Chain 0




ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 20.DEC.2024 11:57:22

802.11n40_2422MHz_Chain 1




ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 20.DEC.2024 14:13:59

802.11n40_2442MHz_Chain 1



ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 20.DEC.2024 14:14:39


802.11n40_2462MHz_Chain 1



ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 20.DEC.2024 14:16:18


100 kHz Bandwidth of Frequency Band Edge 2412~2472

802.11b_2412MHz_Chain 0




ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 5.DEC.2024 14:07:15

802.11b_2472MHz_Chain 0




ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 5.DEC.2024 14:11:43

802.11b_2412MHz_Chain 1




ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 5.DEC.2024 14:50:44

802.11b_2472MHz_Chain 1




ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 5.DEC.2024 14:56:03

802.11g_2412MHz_Chain 0




ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 5.DEC.2024 14:28:50

802.11g_2472MHz_Chain 0




ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 5.DEC.2024 14:34:53


802.11g_2412MHz_Chain 1




802.11g_2472MHz_Chain 1




802.11n20_2412MHz_Chain 0




802.11n20_2472MHz_Chain 0




802.11n20_2412MHz_Chain 1



802.11n20_2472MHz_Chain 1




802.11n40_2422MHz_Chain 0




ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 30.AUG.2024 11:52:09

802.11n40_2462MHz_Chain 0




ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 30.AUG.2024 13:21:19

802.11n40_2422MHz_Chain 1



ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 30.AUG.2024 14:04:24

802.11n40_2462MHz_Chain 1




ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 30.AUG.2024 14:13:32

Duty Cycle

2412~2472

802.11b_2412MHz_Chain 0


8.375ms,8.422ms



ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 3.SEP.2024 15:15:24

802.11b_2442MHz_Chain 0


8.373ms,8.419ms



ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 5.DEC.2024 14:02:14

802.11b_2472MHz_Chain 0


8.368ms,8.415ms



ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 3.SEP.2024 15:13:00

802.11b_2412MHz_Chain 1


8.375ms,8.422ms



ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 3.SEP.2024 15:17:47

802.11b_2442MHz_Chain 1


8.375ms,8.422ms



ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 3.SEP.2024 15:20:11


802.11b_2472MHz_Chain 1

8.375ms,8.422ms




ProjectNo.:2405W66906E-RF Tester:Ryan Zhang
Date: 3.SEP.2024 15:22:32


802.11g_2412MHz_Chain 0
1.391ms,1.437ms




802.11g_2442MHz_Chain 0
1.391ms,1.437ms




802.11g_2472MHz_Chain 0
1.391ms,1.437ms




802.11g_2412MHz_Chain 1
1.391ms,1.437ms




802.11g_2442MHz_Chain 1
1.391ms,1.437ms




802.11g_2472MHz_Chain 1
1.390ms,1.437ms




802.11n20_2412MHz_Chain 0
1.299ms,1.345ms




802.11n20_2442MHz_Chain 0
1.299ms,1.345ms




802.11n20_2472MHz_Chain 0
1.299ms,1.345ms




802.11n20_2412MHz_Chain 1
1.299ms,1.344ms




802.11n20_2442MHz_Chain 1
1.298ms,1.344ms




802.11n20_2472MHz_Chain 1
1.300ms,1.345ms




802.11n40_2422MHz_Chain 0
0.647ms,0.692ms




802.11n40_2442MHz_Chain 0
0.648ms,0.692ms




802.11n40_2462MHz_Chain 0
0.648ms,0.694ms




802.11n40_2422MHz_Chain 1
0.647ms,0.692ms



802.11n40_2442MHz_Chain 1
0.648ms,0.692ms



802.11n40_2462MHz_Chain 1
0.648ms,0.692ms



4 Test Setup Photo

Please refer to the attachment 2405W66906E Test Setup photo.

5 E.U.T Photo

Please refer to the attachment 2405W66906E External photo and 2405W66906E Internal photo.

---End of Report---