



Band 4 5 MHz Low QPSK RB25#0




Date: 1.APR.2022 16:39:40

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 12.MAR.2022 10:56:39

Band 4_5 MHz_Middle_QPSK_RB25#0




Date: 12.MAR.2022 16:34:43

Band 4_5 MHz_Middle_16QAM_RB25#0




Date: 12.MAR.2022 10:57:11

Band 4_5 MHz_High_QPSK_RB25#0




Date: 12.MAR.2022 10:57:36

Band 4_5 MHz_High_16QAM_RB25#0




Date: 12.MAR.2022 10:57:56

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 12.MAR.2022 10:58:20

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 12.MAR.2022 10:58:48

Band 4 10 MHz Middle QPSK RB50#0




Date: 12.MAR.2022 10:59:17

Band 4 10 MHz Middle 16QAM RB50#0




Date: 12.MAR.2022 10:59:39

Band 4_10 MHz_High_QPSK_RB50#0




Date: 12.MAR.2022 11:00:01

Band 4_10 MHz_High_16QAM_RB50#0




Date: 12.MAR.2022 11:00:29

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 12.MAR.2022 11:00:58

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 12.MAR.2022 11:01:26

Band 4_15 MHz_Middle_QPSK_RB75#0




Date: 1.APR.2022 16:41:33

Band 4_15 MHz_Middle_16QAM_RB75#0




Date: 12.MAR.2022 11:02:11

Band 4_15 MHz_High_QPSK_RB75#0




Date: 12.MAR.2022 11:02:48

Band 4_15 MHz_High_16QAM_RB75#0




Date: 12.MAR.2022 11:03:15

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 12.MAR.2022 11:03:50

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 12.MAR.2022 11:04:27

Band 4_20 MHz_Middle_QPSK_RB100#0




Date: 12.MAR.2022 11:04:58

Band 4_20 MHz_Middle_16QAM_RB100#0




Date: 12.MAR.2022 11:05:31

Band 4_20 MHz_High_QPSK_RB100#0




Date: 12.MAR.2022 11:06:02

Band 4_20 MHz_High_16QAM_RB100#0




Date: 12.MAR.2022 11:06:36

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 12.MAR.2022 11:06:55

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 12.MAR.2022 11:07:10

Band 5_1.4 MHz_Middle_QPSK_RB6#0




Date: 12.MAR.2022 11:07:31

Band 5_1.4 MHz_Middle_16QAM_RB6#0




Date: 12.MAR.2022 11:07:46

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 12.MAR.2022 11:08:07

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 12.MAR.2022 11:08:25

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 12.MAR.2022 11:08:44

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 12.MAR.2022 11:08:59

Band 5_3 MHz_Middle_QPSK_RB15#0




Date: 12.MAR.2022 11:09:14

Band 5_3 MHz_Middle_16QAM_RB15#0




Date: 12.MAR.2022 11:09:32

Band 5_3 MHz_High_QPSK_RB15#0




Date: 12.MAR.2022 11:09:50

Band 5_3 MHz_High_16QAM_RB15#0




Date: 12.MAR.2022 11:10:11

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 12.MAR.2022 11:10:30

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 12.MAR.2022 11:10:47

Band 5_5 MHz_Middle_QPSK_RB25#0




Date: 12.MAR.2022 11:11:05

Band 5_5 MHz_Middle_16QAM_RB25#0




Date: 12.MAR.2022 11:11:20

Band 5_5 MHz_High_QPSK_RB25#0




Date: 12.MAR.2022 11:11:38

Band 5_5 MHz_High_16QAM_RB25#0




Date: 12.MAR.2022 11:11:56

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 12.MAR.2022 11:12:25

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 12.MAR.2022 11:12:47

Band 5_10 MHz_Middle_QPSK_RB50#0




Date: 12.MAR.2022 11:13:16

Band 5_10 MHz_Middle_16QAM_RB50#0




Date: 12.MAR.2022 11:13:44

Band 5_10 MHz_High_QPSK_RB50#0



Date: 12.MAR.2022 11:14:10

Band 5_10 MHz_High_16QAM_RB50#0



Date: 12.MAR.2022 11:14:35