



GSM1900 (GSM)								
Channel	Frequency (MHz)	EIRP (dBm)	Limit (dBm)	Over Limit (dB)	S.G. Power (dBm)	TX Cable loss (dB)	TX Antenna Gain (dBi)	Polarization (H/V)
Lowest	3700	-56.29	-13	-43.29	-68.55	2.641	14.90	H
	5550	-54.66	-13	-41.66	-66.52	2.94	14.80	H
	7400	-52.90	-13	-39.90	-62.67	3.39	13.16	H
	3699	-56.22	-13	-43.22	-68.48	2.64	14.90	V
	5550	-54.40	-13	-41.40	-66.26	2.94	14.80	V
	7404	-52.36	-13	-39.36	-62.13	3.39	13.16	V
Middle	3759	-58.42	-13	-45.42	-70.68	2.641	14.90	H
	5640	-53.04	-13	-40.04	-64.90	2.94	14.80	H
	7524	-54.72	-13	-41.72	-64.49	3.39	13.16	H
	3759	-58.23	-13	-45.23	-70.49	2.64	14.90	V
	5640	-51.01	-13	-38.01	-62.87	2.94	14.80	V
	7524	-54.45	-13	-41.45	-64.22	3.39	13.16	V
Highest	3819	-56.83	-13	-43.83	-69.09	2.641	14.90	H
	5729	-54.16	-13	-41.16	-66.02	2.94	14.80	H
	7369	-52.83	-13	-39.83	-62.60	3.39	13.16	H
	3819	-56.52	-13	-43.52	-68.78	2.64	14.90	V
	5730	-54.28	-13	-41.28	-66.14	2.94	14.80	V
	7639	-51.66	-13	-38.66	-61.43	3.39	13.16	V

Remark: Spurious emissions within 30-1000MHz were found more than 20dB below limit line.

GSM1900 (EDGE)								
Channel	Frequency (MHz)	EIRP (dBm)	Limit (dBm)	Over Limit (dB)	S.G. Power (dBm)	TX Cable loss (dB)	TX Antenna Gain (dBi)	Polarization (H/V)
Lowest	3700	-57.09	-13	-44.09	-69.35	2.641	14.90	H
	5550	-54.82	-13	-41.82	-66.68	2.94	14.80	H
	7400	-52.62	-13	-39.62	-62.39	3.39	13.16	H
	3699	-56.81	-13	-43.81	-69.07	2.64	14.90	V
	5550	-54.96	-13	-41.96	-66.82	2.94	14.80	V
	7400	-52.92	-13	-39.92	-62.69	3.39	13.16	V
Middle	3759	-58.30	-13	-45.30	-70.56	2.641	14.90	H
	5640	-56.63	-13	-43.63	-68.49	2.94	14.80	H
	7524	-55.09	-13	-42.09	-64.86	3.39	13.16	H
	3759	-58.24	-13	-45.24	-70.50	2.64	14.90	V
	5640	-57.69	-13	-44.69	-69.55	2.94	14.80	V
	7524	-54.67	-13	-41.67	-64.44	3.39	13.16	V
Highest	3819	-57.50	-13	-44.50	-69.76	2.641	14.90	H
	5730	-54.39	-13	-41.39	-66.25	2.94	14.80	H
	7644	-51.98	-13	-38.98	-61.75	3.39	13.16	H
	3819	-57.15	-13	-44.15	-69.41	2.64	14.90	V
	5729	-54.94	-13	-41.94	-66.80	2.94	14.80	V
	7639	-51.79	-13	-38.79	-61.56	3.39	13.16	V

Remark: Spurious emissions within 30-1000MHz were found more than 20dB below limit line.

—————THE END—————