

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15/IC RSS Certification
2BLAU-ATWR-V4
N/A
24-0179
September 9, 2024
Armillia Tech Ltd
ATWR-V4

EXTERNAL PHOTOS




Figure 1. Front Side

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15/IC RSS Certification
2BLAU-ATWR-V4
N/A
24-0179
September 9, 2024
Armilla Tech Ltd
ATWR-V4



Figure 2. Rear Side

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15/IC RSS Certification
2BLAU-ATWR-V4
N/A
24-0179
September 9, 2024
Armilla Tech Ltd
ATWR-V4



Figure 3. Side 1

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15/IC RSS Certification
2BLAU-ATWR-V4
N/A
24-0179
September 9, 2024
Armilla Tech Ltd
ATWR-V4



Figure 4. Side 2 (Button Side)

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15/IC RSS Certification
2BLAU-ATWR-V4
N/A
24-0179
September 9, 2024
Armilla Tech Ltd
ATWR-V4



Figure 5. Side 3 (Charger Port Side)

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15/IC RSS Certification
2BLAU-ATWR-V4
N/A
24-0179
September 9, 2024
Armillia Tech Ltd
ATWR-V4




Figure 6. Side 4