

## Request for Class II Permissive Change

Regarding: FCC ID: 2AUIUWYZECP2A

Date: 1/12/2022

To: Federal Communication Commission  
Equipment Authorization Branch  
7435 Oakland Mills Road  
Columbia, MD 21046

Please be notified that we, the undersigned, (Wyze Labs, Inc.) declare that the reasons for this Class II permissive change are as below:

Added a magnetic ring at one end of the 1.22 pin cable and fix it with acetic acid tape 2.3 added shielding for pin cable, and the emission degradation occurs.

Sincerely,

Print Name: Roy Zhang

Title: Certification Senior Manager

Signature:



On behalf of Company: Wyze Labs, Inc.

Telephone: 8617600404714

E-mail: roy.zhang@wyze.cn