




Band7_10MHz_QPSK_LCH_2505MHz_RB_50_0_NTNV




Band7_10MHz_QPSK_MCH_2535MHz_RB_50_0_NTNV




Band7 10MHz QPSK HCH 2565MHz RB 50 0 NTNV




Band7 10MHz 16QAM LCH 2505MHz RB 50 0 NTNV




Band7 10MHz 16QAM MCH 2535MHz RB 50 0 NTNV




Band7 10MHz 16QAM HCH 2565MHz RB 50 0 NTNV




Band7_15MHz_QPSK_LCH_2507.5MHz_RB_75_0_NTNV




Band7_15MHz_QPSK_MCH_2535MHz_RB_75_0_NTNV




Band7 15MHz QPSK HCH 2562.5MHz RB 75 0 NTNV




Band7 15MHz 16QAM LCH 2507.5MHz RB 75 0 NTNV




Band7_15MHz_16QAM_MCH_2535MHz_RB_75_0_NTNV




Band7_15MHz_16QAM_HCH_2562.5MHz_RB_75_0_NTNV




Band7 20MHz QPSK LCH 2510MHz RB 100 0 NTNV




Band7 20MHz QPSK MCH 2535MHz RB 100 0 NTNV




Band7 20MHz QPSK HCH 2560MHz RB 100 0 NTNV



Band7 20MHz 16QAM LCH 2510MHz RB 100 0 NTNV



Band7 20MHz 16QAM MCH 2535MHz RB 100 0 NTNV



Band7 20MHz 16QAM HCH 2560MHz RB 100 0 NTNV

