



**Netcom Technology (HK) Limited**

10/F, China Aerospace Centre, 143 Hoi Bun Road,  
Kwun Tong, Kowloon, Hong Kong  
HKTel: 852-23850111

Federal Communications Commission  
7435 Oakland Mills Road  
Columbia, MD 21046

Date: July 10, 2014

Attention: Application Examiner / Review Engineer

Subject: Request to change in identification per section 2.933 of FCC rules

Reference: FCC ID: **PPD-QCASP141**

To The Commission:

This Change of Identification request applies for a new FCC ID: **2AB9Y-GT141GT202** as established in 47CFR 2.933(b) for a currently approved device. This application by **Netcom Technology (HK) Limited** will establish a new FCC ID under **Netcom Technology (HK) Limited** grantee code for purpose of marketing. The original grant to **Qualcomm Atheros, Inc.** will remain in effect.

An authorization letter by **Qualcomm Atheros, Inc.** is attached.  
Per 2.933(b)

1. The original identification is **PPD-QCASP141**. The original grant date is **02/10/2014**.
2. The equipment is electrically identical. Only the FCC ID number is different.
3. The original test results are applicable and representative of this changed device.
4. Exterior photographs are included in this application.

The following files are electronically submitted as attachments:

**Cover Letter**

**External Photos**

**FCC ID label format and location**

Sincerely yours,

Jenny Liu/ quality supervisor  
Netcom Technology (HK) Limited  
Tel: (86-755)-86168848-1920  
Fax: (86-755)-86169388  
e-mail: jenny.liu@netcom-3c.com