

Labeling Declaration Letter

Date: January 2, 2019

FCC ID: 2AEUPBHAMS001

Model Number: 5SM1S8

Following the KDB 784748 D01 General labeling and Notification, the information related to Labeling implementation for the **Motion Sensor**, FCC ID: 2AEUPBHAMS001

Information	On Product	On Product Packaging	In Online User Guide	In Printed User Guide
FCC ID Number	Yes	Yes	No	No
15.19 Statement “This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation”	No	Yes	No	Yes
Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment	No	No	No	Yes

Product Packaging Label is shown below:

FCC ID: 2AEUPBHAMS001

This device complies with Part 15 of the FCC Rules.

Operation is subject to the following two conditions:

- (1) this device may not cause harmful interference, and
- (2) this device must accept any interference received,

The product is packaged individually.

Should you have any questions or comments regarding this matter, please have my best

Ring LLC

1523 26th Street, Santa Monica, California 90404, United States
attention.

Sincerely,

A handwritten signature in dark ink, appearing to read "Michael Recker". The signature is fluid and cursive, with the first name "Michael" being more legible than the last name "Recker".

(Signed)

Name / Title: Michael Recker / CTO, Ring Beams

Company: Ring LLC

Address: 1523 26th Street, Santa Monica, California 90404, United States

Phone: 8006561918

Fax: 3102272217

E-Mail: michael.recker@ring.com