
FCC TEST REPORT Report No.: F370214

1.1. Photographs of Conducted Powerline Test Configuration

The photographs show the configuration that generates the maximum emission.



FRONT VIEW



FCC ID

: EUN-R02501

REAR VIEW

SPORTON International Inc. TEL: 886-2-2696-2468

Page No.: 1 of 3 FAX: 886-2-2696-2255 Issued : Sep. 09, 2003 FCC TEST REPORT Report No.: F370214



SIDE VIEW

FCC ID : EUN-R02501 SPORTON International Inc. TEL: 886-2-2696-2468

Page No. : 2 of 3 Issued : Sep. 09, 2003 FAX: 886-2-2696-2255


FCC TEST REPORT Report No.: F370214

1.2. Photographs of Radiated Emission Test Configuration

• The photographs show the configuration that generates the maximum emission.



FRONT VIEW



REAR VIEW

SPORTON International Inc. TEL: 886-2-2696-2468

FAX: 886-2-2696-2255

FCC ID : EUN-R02501

Page No.: 3 of 3

Issued : Sep. 09, 2003