






Plot on Channel 6525 MHz




Plot on Channel 6565 MHz



Plot on Channel 6685 MHz




Plot on Channel 6845 MHz






Plot on Channel 6885 MHz




10:56:35 PM 12/18/2023

Plot on Channel 6925 MHz




11:00:20 PM 12/18/2023

Plot on Channel 7005 MHz



11:02:54 PM 12/18/2023

Plot on Channel 7085 MHz




11:09:23 PM 12/18/2023




EUT Mode 802.11be EHT40 52OFDMA RU8

Plot on Channel 6125 MHz




02:59:19 AM 12/20/2023

Plot on Channel 6285 MHz




03:59:03 AM 12/20/2023

Plot on Channel 6405 MHz



03:49:26 AM 12/20/2023


Plot on Channel 6445 MHz




03:59:04 AM 12/20/2023




Plot on Channel 6485 MHz




Plot on Channel 6525 MHz



Plot on Channel 6565 MHz




Plot on Channel 6685 MHz







Plot on Channel 6845 MHz




Plot on Channel 6885 MHz



Plot on Channel 6925 MHz




Plot on Channel 7005 MHz





Plot on Channel 7085 MHz






EUT Mode


802.11be EHT80 Full RU

Plot on Channel 6145 MHz




11:18:59 PM 12/18/2023

Plot on Channel 6305 MHz




11:33:54 PM 12/18/2023

Plot on Channel 6385 MHz



11:36:39 PM 12/18/2023


Plot on Channel 6465 MHz




11:39:47 PM 12/18/2023




Plot on Channel 6545 MHz




Plot on Channel 6625 MHz



Plot on Channel 6705 MHz




Plot on Channel 6785 MHz







Plot on Channel 6865 MHz



Plot on Channel 6945 MHz



Plot on Channel 7025 MHz







EUT Mode

802.11be EHT80 52OFDMA RU16


Plot on Channel 6145 MHz




Plot on Channel 6305 MHz



Plot on Channel 6385 MHz




Plot on Channel 6465 MHz







Plot on Channel 6545 MHz




Plot on Channel 6625 MHz



Plot on Channel 6705 MHz




Plot on Channel 6785 MHz







Plot on Channel 6865 MHz



Plot on Channel 6945 MHz



Plot on Channel 7025 MHz






EUT Mode


802.11be EHT80 Puncture20 1

Plot on Channel 6145 MHz




12:20:26 AM 12/21/2023

Plot on Channel 6305 MHz




12:47:52 AM 12/21/2023

Plot on Channel 6385 MHz



12:56:26 AM 12/21/2023


Plot on Channel 6465 MHz



01:13:34 AM 12/21/2023




Plot on Channel 6545 MHz




01:23:39 AM 12/21/2023

Plot on Channel 6625 MHz




01:28:52 AM 12/21/2023

Plot on Channel 6705 MHz



01:52:29 AM 12/21/2023


Plot on Channel 6785 MHz




02:03:11 AM 12/21/2023




Plot on Channel 6865 MHz



Plot on Channel 6945 MHz



Plot on Channel 7025 MHz






EUT Mode


802.11be EHT160 Full RU

Plot on Channel 6185 MHz




12:19:53 AM 12/19/2023

Plot on Channel 6345 MHz




12:22:58 AM 12/19/2023

Plot on Channel 6505 MHz



12:25:54 AM 12/19/2023


Plot on Channel 6665 MHz



12:39:02 AM 12/19/2023



Plot on Channel 6825 MHz



Plot on Channel 6985 MHz

